



OPEL GRANDLAND: GF-979-DB

Vinnumber:	W0VZCYHZ0N6804793	Versionname:	OPEL GRANDLAND 1.5 DIESEL 130 ELEGANCE BUSINESS AUTO VP [5P] bva 8-131CH-7cv (SUV)
First Registrationdate:	10/03/2022	Fiscalpower:	
Expertise Mileage:	113682	Power Kw:	96
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control	Lining Other	
		Lining Semi-leather	

Tyres


	225/55/18/102 V			
Summer tyres:	Fr.L.	Michelin: 20%	Fr.R.	Michelin: 20%
	Re.L.	Michelin: 20%	Re.R.	Michelin: 20%
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Tear, Replace




Wing RL, Dent(s) and scratch(es), Repair and paint (complete)




Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Wing trim RR, Scratch(es), Paint



Door RR, Scratch(es), Paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: GF-979-DB Date de 1ère immatriculation: 10/03/2022

Modèle: Opel GRANDLAND 1.5 DIESEL 130 ELEGANCE BUSINESS AUTO VP [5P] bva 8-131CH-7cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
04/07/2025	101.797	SODILINE	REVISION
07/11/2024	86.430	SODILINE	BATTERIE RPLT
15/03/2024	71.223	SODILINE	LIQUIDE DE FREIN
	0		DIVERS FREIN
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM ET AIR ET CARBURANT
13/06/2023	51.275	TRUJAS SAS	REVISION
18/11/2022	28.918	TRUJAS SAS	REVISION