

INSPECTION REPORT


End of contract

GENERAL INFO

File	311827
License plate	2AXM220
Vehicle identification number	WF0JXXWPCHEMA55649
Dossier	2021118131
Make	Ford S-Max 2.5iHEV 190 Titaniu
Mileage	79110
First registration	27/08/2021
client availability date	07/05/2026
inspectionDate	27/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
124	Light / Rear left / Replace	N
125	Light / Rear Left On Rear Bonnet / Replace	N
152	Rear Bonnet // Smart Repair Large	N
11	Bumper Front // Smart Repair Medium	N
65	Wing Front Left // Replace & Painting	N
82	Door Front Left // Smart Repair Large	N
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
157	Rear Bonnet / Trim / Replace	Y
162	Roof // Painting	N
170	Roof / Full Panoramic Roof Medium / Replace	N
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	N
181	Wing Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	N
236	Wing Front right // Polish	Y
540	Interior // Repair 1	Y
543	Interior // Ionization Odor	N
561	Dashboard // Repair	Y
568	Dashboard / Ventilation Outlet / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	Y

Damage Pictures



Damage within Renta-norm-



Door Front Left // Smart Repair Large-scratch + dent






Interior Cleaning // Small-stain



Interior // Repair 1-bad position



Dashboard / Ventilation Outlet / Replace-bad position




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch




Dashboard // Repair-scratch



Door Front Right // Painting-scratch



Bumper Rear // Painting-scratch



Wing Rear Right // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rear Bonnet / Trim / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch




Light / Rear Right / Replace-scratch



Wing Rear Left // Painting-scratch



Roof // Painting-scratch




Roof / Full Panoramic Roof Medium / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Wing Front right // Polish-scratch



Light / Rear left / Replace-scratch



Rear Bonnet // Smart Repair Large-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Wing Front Left // Replace & Painting-cracked



Bumper Front // Smart Repair Medium-scratch + dent