MACADAM









AUDI A5 SPORTBACK: GB-416-WR

Vinnumber:	**WAUZZZF55MA053178**	Versionname:	**AUDI A5 SPORTBACK 35 TDI 163 S TRONIC 7 BUSI LINE SB VP [5P] bva 7-163CH-9cv (bi-corps)**
First Registrationdate:	**20/09/2021**	Fiscalpower:	
Expertise Mileage:	**102979**	Power Kw:	**120**
Bodytype:	**Coupé**	Body colour	**Dark Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**245/40/18/933 Y**			
	Fr.L.	**Pirelli: 40%**	Fr.R.	**Pirelli: 40%**
	Re.L.	**Pirelli: 35%**	Re.R.	**Pirelli: 40%**

Tyre profile depth FL	**5.6**
Tyre profile depth FR	**5.5**
Tyre profile depth RL	**5.8**
Tyre profile depth RR	**5.7**
Tyre size FL	**245/40 R 18 933 Y**
Tyre size FR	**245/40 R 18 933 Y**
Tyre size RL	**245/40 R 18 933 Y**
Tyre size RR	**245/40 R 18 933 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Interior, Stain, Cleaning





Alloy rim FL, Scratch(es), Repair/replace (lump sum)





Alloy rim RL, Scratch(es), Repair/replace (lump sum)





Alloy rim RR, Scratch(es), Replace






Alloy rim FR, Scratch(es), Repair/replace (lump sum)





Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Paint




Bumper F, Deformed / Strained, Repair and paint (complete)





Bumper moulding FR, Scratch(es), Replace




Wing RR, Scratch(es), Paint




Door RR, Dent(s) and scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Paint




Sill trim R, Deformed / Strained, Replace and paint




Wing FR, Dent(s) and scratch(es), Repair and paint (complete)




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)







Bumper R, Deformed / Strained, Repair and paint (complete)




Bumper moulding R, Deformed / Strained, Replace




ALPHABET

Historique Maintenance

Immatriculation: **GB-416-WR** Date de 1ère immatriculation: **20/09/2021**

Modèle: **Audi A5 SPORTBACK 35 TDI 163 S TRONIC 7 BUSI LINE SB VP [5P] bva 7-163CH-9cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
08/07/2026	96.328	BAUER NANTERRE	DIAG
			Main D'œuvre
			Fluide
			Liquide ADBLUE (Remplacement)
			Téléchargement logiciel
			Main D'œuvre
			ESSAI
			ADBLUE
			TELECHARGEMENT CALCULATEUR
20/03/2026	88.500	VGRF GRAND PARIS	DISQUES PLAQUETTES AR RPLT
			REVISION
			FILTRE CLIM RPLT
			FILTRE A AIR RPLT
			ADBLUE
			LIQUIDE LAVE GLACE
			RECYCLAGE
24/09/2025	81.216	VGRF GRAND PARIS	DIVERS ECHAPPEMENT
21/08/2025	79.842	VGRF GRAND PARIS	RADIO GPS RPLT
			VANNE EGR RPLT
21/07/2025	79.842	VGRF GRAND PARIS	BATTERIE RPLT
			RECYCLAGE
			LEVE VITRE AVG RPLT
			DISQUES PLAQUETTES AV RPLT
			PILE DE CLE RPLT
			LIQUIDE DE FREIN
21/07/2025	79.842	VGRF GRAND PARIS	REMPLACEMENT PNEUS ETE
			POSE EQUILIBRAGE ROUES
21/10/2024	65.451	ENTREPRISE BAUER	REMPLACEMENT PNEUS ETE
21/10/2024	65.451	ENTREPRISE BAUER	GEOMETRIE CTRL
16/05/2024	58.472	ENTREPRISE BAUER	BALAIS ESSUIE GLACE AV
			REVISION ET CLIM ET AIR ET CARBURANT
			DISQUES PLAQUETTES AR RPLT

Historique Maintenance

Immatriculation: **GB-416-WR** Date de 1ère immatriculation: **20/09/2021**

Modèle: **Audi A5 SPORTBACK 35 TDI 163 S TRONIC 7 BUSI LINE SB VP [5P] bva 7-163CH-9cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
			ADBLUE
			HUILE BV RPLT
23/08/2023	44.388	CENTRE AUTO TARNAIS	APPOINT D HUILE
			LIQUIDE DE FREIN
			LIQUIDE LAVE GLACE
			PLAQUETTES AV RPLT
12/07/2023	41.551	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
03/11/2022	28.978	ALIANTIS	BALAIS ESSUIE GLACE AV
			REVISION
			REVISION
06/07/2022	19.294	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE