MACADAM










Renault Clio: R652NH

Vinnumber:	**VF1RJA00369818254**	Versionname:	**Clio 1.6 Hybrid 103kW R.S. Line automaat**
First Registrationdate:	**24/10/2022**	Fiscalpower:	
Expertise Mileage:	**89051**	Power Kw:	**68**
Bodytype:		Body colour	**Blanc Glacier niet-metaallak**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**362**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Rear parking sensors	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 45 / 17 / 88 / V / Aluminium	6,1 mm	Continental	Summer
	Right	205 / 45 / 17 / 88 / V / Aluminium	5,5 mm	Continental	Summer
Rear	Left	205 / 45 / 17 / 88 / Y / Aluminium	7,1 mm	Continental	Summer
	Right	205 / 45 / 17 / 88 / Y / Aluminium	7,1 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	**0**

Door FL, Dent(s), Repair and paint (complete)




Door RL, Bad repair, Repair and paint (complete)






Wing RL, Dent(s), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Replace




Bumper F, Scratch(es), Repair and paint (complete)




Door RR, Dent(s), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VF1RJA00369818254

ALPHABET

Kenteken	R652NH
Merk Model	Renault Clio 1.6 Hybrid 103kW R.S. Line automaat
Brandstofsoort	Benzine
Datum deel1	10/24/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/30/26	85,975	APK
9/30/26	85,975	Ruitenwisserblad(en) voorzijde
9/30/26	85,975	Sleutelbatterij
9/30/26	85,975	Vervanging band
4/8/26	66,910	Bougie
4/8/26	66,910	Luchtfilter
4/8/26	66,910	Onderhoudsbeurt
4/8/26	66,910	Remvloeistof
4/8/26	66,910	Ruitenwisserblad(en) voorzijde
4/8/26	66,910	Vervanging band
3/25/26	65,362	Reparatie band(en)
7/11/25	51,878	Onderhoudsbeurt
11/6/24	38,529	Vervanging band
8/13/24	34,120	Onderhoudsbeurt
9/22/23	18,660	Onderhoudsbeurt