MACADAM








FIAT Fiorino: 0527-LSF

Vinnumber:	**ZFA22500006V11586**	Versionname:	**Cargo SX N1 1.3 MJet 70 kW (95 CV) furgón derivado de turismo 70kW 4P manual**
First Registrationdate:	**29/07/2021**	Fiscalpower:	
Expertise Mileage:	**121923**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Roof rack	
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Goodyear: 6 mm**	Fr.R.	**Goodyear: 6 mm**
	Re.L.	**Goodyear: 7 mm**	Re.R.	**Goodyear: 7 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**105/65 R 15 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Cleaning




Boot lid covering R, Broken, Replace





Partition wall, Scratch(es), Paint




Seat cover FL, Worn, Replace




Registration document, Missing, Repair/replace (lump sum)

User's manual, Missing, Repair/replace (lump sum)




Malfunction indicator, Blinking, Check




Door FL, Scratch(es), Paint




Bonnet, Dent(s), Acceptable




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)




Rear panel, Scratch(es), Repair and paint (complete)




Bumper R, Bump, Repair and paint (complete)





Boot door panel RL, Dent(s), Repair and paint (complete)




Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)




Tyres, No damage, Check






Aerial, Missing, Replace




ALPHABET

Datos del vehículo

Marca	FIAT	Matrícula	0527-LSF
Modelo	Fiorino	VIN	ZFA22500006V11586
Versión	Cargo SX N1 1.3 MJet 70 kW (95 CV) furgón derivado de turismo 70kW 4P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
29/11/2022	Servicio Aceite	30900	PSA RETAIL VALENCIA-TRES CRUCES
24/11/2022	Sustitución	30905	EUROMASTER (P211)
05/06/2024	Rev. 60.000 kms	63335	AUTOMOVILES SAGUNTO S.A.
14/05/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter, Desmontar y montar Rueda tr iz, Escobilla dr limpiaparabrisas, Escobilla iz limpiaparabrisas, Filtro aceite - PURFLUX - Nueva, Filtro aire, Filtro antipolen - Nueva, Filtro combustible, Lámpara freno tr dr, Lámpara intermitente dl dr - Nueva, Líquido frenos - DOT4 OEM1 - Nueva, Líquido lavaparabrisas, Másticos, Pastillas freno dl - Nueva, Serv inspección 4º año, Sustituir Aceite motor / Sustituir Filtro aceite, Sustituir Escobillas limpiaparabrisas, Sustituir Lámpara freno tr dr, Sustituir Lámpara intermitente dl dr, Sustituir Líquido frenos, Sustituir Líquido lavaparabrisas, Sustituir Másticos, Sustituir Pastillas freno dl, Tasa de gestión de aceites usados	94072	AUTOMOVILES MEXUR S.L.
04/06/2025	Alineado sencillo, Ecotasa - N2, Goodyear / 542445 195/65X15 GYEAR.EFIG.PERF2 91H, Sustitucion y kit de montaje	96683	Juan García Torrecilla
16/06/2025	Ecotasa - N2, Goodyear / 542445 195/65X15 GYEAR.EFIG.PERF2 91H, Sustitucion y kit de montaje	98444	NEUMÁTICOS SOLEDAD (PUERTO DE SAGUNTO)
24/10/2025	Batería - Nueva, Sustituir Batería	106235	AUTOMOVILES SAGUNTO S.A.

Fecha	Descripción	Kilómetros	Taller