



Volvo V60: P135LP

Vinnumber:	YV1ZWH1VDN1492354	Versionname:	V60 Recharge T6 2.0 250kW 4WD Inscription Expression auto
First Registrationdate:	21/04/2022	Fiscalpower:	
Expertise Mileage:	144787	Power Kw:	186
Bodytype:		Body colour:	Pebble Grey (metallic)
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	545
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 45 / 18 / 98 / Y / Aluminium	4,4 mm	Bridgestone	Summer
	Right	235 / 45 / 18 / 98 / Y / Aluminium	4,5 mm	Bridgestone	Summer
Rear	Left	235 / 45 / 18 / 98 / Y / Aluminium	4,5 mm	Bridgestone	Summer
	Right	235 / 45 / 18 / 98 / Y / Aluminium	5,5 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Wing FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	P135LP
Merk Model	Volvo V60 Recharge T6 2.0 250kW 4WD Inscription Expression auto
Brandstofsoort	Benzine
Datum deel1	21-04-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
01-05-26	139.787	Uitlijnen voor en achterwielen
20-04-26	139.152	APK
20-04-26	139.152	Ruitenwischerblad(en) voorzijde
31-10-25	124.752	Bougie
31-10-25	124.752	Luchtfilter
31-10-25	124.752	Onderhoudsbeurt
31-10-25	124.752	Volvo Check aandrijving
31-10-25	124.752	Volvo Check slijtagedelen
16-08-25	0	Vervanging band
05-03-25	100.830	Ruitenwischerblad(en) voorzijde
16-12-24	95.564	Extra verwarmingselement
16-12-24	95.564	Onderhoudsbeurt
16-12-24	95.564	Remvloeistof
16-12-24	95.564	Volvo Check slijtagedelen
16-01-24	60.537	Bougie
16-01-24	60.537	Luchtfilter
16-01-24	60.537	Onderhoudsbeurt
16-01-24	60.537	Ruitenwischerblad(en) voorzijde
16-01-24	60.537	Volvo Check aandrijving
16-01-24	60.537	Volvo Check slijtagedelen
16-03-23	28.979	Onderhoudsbeurt
16-03-23	28.979	Volvo Check slijtagedelen
30-01-23	24.705	Ruitenwischerblad(en) voorzijde