



DACIA DUSTER: FN-767-AA

Vinnumber:	VF1HJD40363586684	Versionname:	DACIA DUSTER Confort Blue dCi 115 4x4 (transfo)
First Registrationdate:	13/01/2020	Fiscalpower:	VF [5P] 6-115CH-6cv (SUV VU)
Expertise Mileage:	142727	Power Kw:	85
Bodytype:	SUV	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Aluminium		
Category:	VS		

Options

Number of keys total	1	Tow bar	
Number keys remote	1	Radio	
Windows electric F		Rear parking sensors	
Windows electric R		Roof bar black	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	215/65/16/98 H			
Summer tyres:	Fr.L.	Kleber: 50%	Fr.R.	Kleber: 50%
	Re.L.	Kleber: 30%	Re.R.	Kleber: 45%
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.2
Tyre profile depth RR				5.3
Tyre size FL				215/65 R 16 98 H
Tyre size FR				215/65 R 16 98 H
Tyre size RL				215/65 R 16 98 H
Tyre size RR				215/65 R 16 98 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Wing FL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)




Door RL, Dent(s) and scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Paint



Door RR, Scratch(es), Paint



Bumper corner RL, Deformed / Strained, Replace and paint



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: **FN-767-AA** Date de 1ère immatriculation: **13/01/2020**

Modèle: **Dacia DUSTER Confort Blue dCi 115 4x4 (transfo) VF [5P] 6-115CH-6cv (SUV VU)**

Date	Kilométrage	Fournisseur	Descriptif
24/02/2026	134.216	SIMONNEAU AUTOMOBILES	ADBLUE
	0		PLAQUETTES AV RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
10/06/2025	121.643	SARL ARCH'AUTO	REVISION
	0		LAMPE AR RPLT
	0		LAMPE CODE AVD RPLT
04/04/2025	118.623	CONTROLE TECHNIQUE DES GRANDS CHAMPS	CONTROLE TECHNIQUE
14/03/2025	117.717	SIMONNEAU AUTOMOBILES	LIQUIDE DE REFROIDISSEMENT RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
	0		DIVERS FREIN
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		BATTERIE RPLT
17/01/2024	105.153	SIMONNEAU AUTOMOBILES	REVISION ET CLIM
25/01/2023	92.505	SIMONNEAU AUTOMOBILES	REVISION
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
17/11/2022	86.985	SIMONNEAU AUTOMOBILES	LIQUIDE DE FREIN
25/11/2021	62.149	SIMONNEAU AUTOMOBILES	LAMPE RPLT
	0		BALAI ESSUIE GLACE AV
	0		REVISION
	0		BALAI ESSUIE GLACE AR
03/02/2021	30.637	SIMONNEAU AUTOMOBILES	REVISION