MACADAM








Mercedes A-Klasse (UKL): 2CRB173

Vinnumber:	**W1K3F8GB3PV157719**	Versionname:	**A250e Business Line 1.3i 218pk/cv 5p 7G-DCT**
First Registrationdate:	**25/10/2022**	Fiscalpower:	
Expertise Mileage:	**45865**	Power Kw:	**118**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**25days**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/17/91 W**			
	Fr.L.	**Continental: 4 mm**	Fr.R.	**Continental: 3 mm**
	Re.L.	**Continental: 4 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 17 91 W**
Tyre size FR	**205/55 R 17 91 W**
Tyre size RL	**205/55 R 17 91 W**
Tyre size RR	**205/55 R 17 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**1**		
Number of charging cables (rapid charge)	**1**		

Centre console, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Replace






Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable







Door RR, Scratch(es), Acceptable


Door FR, Scratch(es), Acceptable




Onderhoudshistorie van: W1K3F8GB3PV157719

ALPHABET

Kenteken	2CRB173
Merk Model	Mercedes A250e Business Line 1.3i 218pk/cv 5p 8G-DCT
Brandstofsoort	Benzine
Datum deel1	10/25/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/21/25	36,270	bougie	Vervangen
11/21/25	36,270	klein materiaal	
11/21/25	36,270	luchtfilter	Vervangen
11/21/25	36,270	mercedes assyst a	Uitvoeren
11/22/24	22,482	klein materiaal	
11/22/24	22,482	mercedes assyst b	Uitvoeren
11/22/24	22,482	remvloeistof	Vervangen
11/22/24	22,482	ruitenwisserrubber vooraan	Vervangen
11/17/23	11,837	klein materiaal	Uitvoeren
11/17/23	11,837	mercedes assyst a	Uitvoeren
11/17/23	11,837	ruitenwisserrubber vooraan	Vervangen
9/4/23	9,676	klein materiaal	Uitvoeren