



Skoda Karoq: [REDACTED]

Vinnumber:	TMBJF7NU0N5061091	Versionname:	
First Registrationdate:	9/06/2022	Fiscalpower:	
Expertise Mileage:	130828	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2602
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/94 V				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1692,80
Interior, Damaged, Acceptable:	0,00



Interior, Dirty, Cleaning 175,04



Bumper moulding F, Scratch(es), Replace 57,90



Step L, Dent(s) and scratch(es), Spot repair 148,33



Wing RL, Scratch(es), Repair and paint (complete) 517,89



Door RL, Dent(s), Acceptable 0,00



A-pillar left, Dent(s) and scratch(es), Spot repair 148,33





Sill trim L, Dent(s), Acceptable 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Bumper trim R, Scratch(es), Smart repair 116,69



Rear window, Scratch(es), Polish 77,26



Tailgate / Boot, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00



Door FR, Dent(s), Paintless dent repair 95,47



Alloy rim FR, Scratch(es), Acceptable 0,00

