



Volkswagen ID.3: S813FN

Vinnumber:	WVWZZZE1ZPP022563	Versionname:	Sneller en extra scherp ID.3 107kW / 62kWH Pro automaat
First Registrationdate:	29/12/2022	Fiscalpower:	
Expertise Mileage:	40516	Power Kw:	107
Bodytype:		Body colour	Mangan Grey
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	803
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		Rear view camera
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 95 / H / Aluminium	5,7 mm	Goodyear	Summer
	Right	215 / 55 / 18 / 95 / H / Aluminium	5,2 mm	Goodyear	Summer
Rear	Left	215 / 55 / 18 / 95 / H / Aluminium	5,1 mm	Goodyear	Summer
	Right	215 / 55 / 18 / 95 / H / Aluminium	4,0 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Outside rear-view mirror housing L, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)



Kenteken	S813FN
Merk Model	Volkswagen Sneller en extra scherp ID.3 107kW / 62kWH Pro automatisch
Brandstofsoort	Elektrisch
Datum deel1	29-12-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
03-03-25	28.435	Onderhoudsbeurt
03-03-25	28.435	Remvloeistof
03-03-25	28.435	Ruitenwischerblad(en) achterzijde
03-03-25	28.435	Ruitenwischerblad(en) voorzijde
01-09-23	15.221	Vervanging band