



Expertise

Protocol number: 46354219
Order No. / Reference: 26600861
Inspection date: 7 Jul 2026

Manufacturer: Ford	Model: S-Max 2.0 EcoBlue Allrad Aut. ST-LINE
VIN: WF0JXXWPCJNM10557	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford S-Max 2.0 EcoBlue Allrad Aut. ST-LINE	
Vehicle Identification number	WF0JXXWPCJNM10557
Mileage (Read)	168,373 km
First registration	5 Oct 2022
Number of holders	1
Next periodical technical inspection	09/2027
(Report not on hand)	
Power / Engine displacement	140 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Van
Colour / colour code	Polar-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Red



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	
Last service on / at	06/2026 at 167,835 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP428742
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BQS 00259		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,635 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R18 101V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	235/50 R18 101V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Uniroyal	5mm / 5mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Uniroyal	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments
- Ambient lighting at the front
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- third brake light
- Black woven fabric headliner
- Roof rails, black
- Tachometer
- Electronic Shifter
- Lane keeping assist including lane keeping assist and driver fatigue warning
- High Beam Assist
- Ford Easy Fuel
- Ford Power Start function
- Ford Power start function with Ford Key Free system
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- rear window wiper
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Steering wheel: Steering column, adjustable in height and reach
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Front and rear parking pilot system
- Upholstery: Leather/fabric with a suede look
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Front sports seats
- Start-stop system
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Cigarette lighter
- All-wheel drive
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 18 alloy wheels (4) with 235/50 R 18 tires
- Body styling kit
- Brake calipers, painted red
- roof console
- Diesel particulate filter (DPF)
- Front door sill trims with ST-Line design
- Driver information system display 25.4 cm color
- Chassis: Sport chassis
- Electric windows front and rear
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Rear spoiler
- Interior mirror, automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Steering wheel: Multifunction leather steering wheel
- Steering wheel: Paddle shifters on the steering wheel
- Front center console with padded armrest
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect
- Package: Winter
- Pedal assembly with aluminum pads
- Tire repair kit
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Electromechanical power steering
- Seats: Flexible seating system "FoldFlatSystem (FFS)"
- Seats: Front seats can be heated individually and variably.
- 230 volt socket
- Bumpers painted in body color
- Trays on the front seatbacks
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control



Extra equipment

- Detachable towbar (including ESP trailer stabilization)
 - Fuel-operated auxiliary heater (including remote control and heated windscreen)
 - Luggage compartment protective grille
 - Paint finish: Metallic
 - Sunshades in the rear side doors (manual)
- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat cover - left side - Porous / cracked - Smart repair
2	Engine	Engine - Leaking - Perform diagnosis
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
6	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
7	Front bumper	Front bumper - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Door - front right side	Door - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Separation net (Trenngitter)



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 6 Nov 2024	5.215,06 €
2	Roof, Front, Rear, Side - left, Side right, Provided by user / customer, from 8 Jun 2024	7.460,39 €

Repainting

No.	Repainting
1	Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Damage 1: Seat - front: Seat cover - left side - Porous / cracked - Smart repair



Damage 1: Seat - front: Seat cover - left side - Porous / cracked - Smart repair




Damage 2: Engine: Engine - Leaking - Perform diagnosis




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 7: Front bumper: Front bumper - Deformed - Repair and paint



Damage 7: Front bumper: Front bumper - Deformed - Repair and paint



Damage 7: Front bumper: Front bumper - Deformed - Repair and paint




Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side




Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Repainting 1: Roof, Bonnet, Side panel - rear left side, Door - rear left side, Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0JXXWPCJNM10557
Hersteller / Modell: FORD FORD S-Max 2.0 EcoBlue Allrad Aut. ST-LINE

Datum	KM-Stand	Beschreibung
08.06.2026	167.835	Motoröl b. Wartung; Regelwartungsdienst
19.02.2026	149.103	Getriebeöl ern/prüfen; Systemtest/Eigendiagnose
30.01.2026	146.594	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
15.01.2026	141.884	Systemtest/Eigendiagnose
17.11.2025	134.674	Systemtest/Eigendiagnose
03.11.2025	132.987	Batterie ern; Systemtest/Eigendiagnose
30.09.2025	129.418	AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.09.2025	126.732	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
11.08.2025	120.355	Systemtest/Eigendiagnose
07.04.2025	108.555	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.07.2024	81.441	Motoröl b. Wartung; Regelwartungsdienst
19.04.2024	70.597	Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Reparatur Sonstiges; Systemtest/Eigendiagnose
13.12.2023	57.269	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.11.2023	55.408	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
23.05.2023	31.802	Motoröl b. Wartung; Regelwartungsdienst