MACADAM








Skoda Kodiaq (KKL): 2BCN562

Vinnumber:	**TMBJB7NS8N8007210**	Versionname:	**Kodiaq Clever 1.5TSi 150pk/cv 5p**
First Registrationdate:	**1/10/2021**	Fiscalpower:	
Expertise Mileage:	**131515**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/17/99 V**			
	Fr.L.	**Bridgestone: 2 mm**	Fr.R.	**Bridgestone: 2 mm**
	Re.L.	**Michelin: 4 mm**	Re.R.	**Michelin: 3 mm**

Tyre profile depth FL	**2.0**
Tyre profile depth FR	**2.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**215/65 R 17 99 V**
Tyre size FR	**215/65 R 17 99 V**
Tyre size RL	**215/65 R 17 99 V**
Tyre size RR	**215/65 R 17 99 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Floor covering FL, Worn, Acceptable




Seat cover FL, Worn, Acceptable




Bonnet, Stone chip(s), Acceptable






Bumper moulding F, Dent(s) and scratch(es), Acceptable





Windscreen, Repaired, No repair




Alloy rim FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Door RL, Dent(s) and scratch(es), Acceptable





Wing trim RL, Scratch(es), Acceptable





Alloy rim RL, Scratch(es), Acceptable




Wing RL, Scratch(es), Acceptable



Wing RL, Repaired, Check



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Repaired, Check



Bumper R, Dent(s) and scratch(es), Acceptable



Reflector, Scratch(es), Replace



Wheel aperture RR, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Acceptable






Wing trim RR, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Repair and paint (complete)






Onderhoudshistorie van: TMBJB7NS8N8007210

ALPHABET

Kenteken	2BCN562
Merk Model	Skoda Kodiaq Clever 1.5TSi 150pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/1/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/10/26	116,984	Inspectie met olieververvanging (vast in	Uitvoeren
9/10/26	116,984	klein materiaal	
9/10/26	116,984	ruitenwisservloeistof	Bijvullen/-laden
5/23/25	85,456	bougie	Vervangen
5/23/25	85,456	Inspectie met olieververvanging (vast in	Uitvoeren
5/23/25	85,456	klein materiaal	
5/23/25	85,456	koelwatervloeistof	Bijvullen/-laden
5/23/25	85,456	luchtfilter	Vervangen
5/23/25	85,456	remblokken vooraan	Vervangen
5/23/25	85,456	remvloeistof	Vervangen
5/23/25	85,456	ruitenwisserrubber achter	Vervangen
5/23/25	85,456	ruitenwisserrubber vooraan	Vervangen
5/23/25	85,456	ruitenwisservloeistof	Bijvullen/-laden
2/12/24	54,934	batterij	Vervangen
2/12/24	54,934	Inspectie met olieververvanging (vast in	Uitvoeren
2/12/24	54,934	klein materiaal	
2/12/24	54,934	luchtfilter interieur	Vervangen
2/12/24	54,934	remblokken achter	Vervangen
2/12/24	54,934	remvloeistof	Vervangen
2/12/24	54,934	ruitenwisserrubber achter	Vervangen
2/12/24	54,934	ruitenwisserrubber vooraan	Vervangen
2/12/24	54,934	ruitenwisservloeistof	Bijvullen/-laden