

2-FAW-659

2-FAW-659 · TS 1.8 Hybrid Dynamic + Business pack · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAW-659	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	SB1ZB3AE20E062598
Model	Corolla Touring Sports	Cylinder Capacity	1.798 ^{cm3}
Model Versions	TS 1.8 Hybrid Dynamic + Business pack	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-03-2024
Color	Black	Odometer	66.940 ^{Km}
Paint Type	Metallic	Numer Of Keys	1
Production Year	2024	Interior	Grey
KW	72	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 22-07-2026

Last maintenance odometer 66.171

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Front Right	3 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part
Frontdoor – Right

Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Fender – Front Right

Damage Type
Small dent(s)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper – Front

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part

Damage Type

Repair Type


Acceptable

Hood

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Left

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

small dents / small scratches

Restyle

No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Sleutel	Replace	No