



RENAULT EXPRESS: 4032-MCF

Vinnumber:	VF1RJK00X70098981	Versionname:	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	11/11/2022	Fiscalpower:	
Expertise Mileage:	171151	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	1	Radio:	
Number keys remote:	1	Roof rack:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/88 T				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				185/65 R 15 88 T
Tyre size FR				185/65 R 15 88 T
Tyre size RL				185/65 R 15 88 T
Tyre size RR				185/65 R 15 88 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------


User's manual, Missing, Repair/replace (lump sum)




Service book, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Ignition key, Broken, Repair/replace (lump sum)



Interior, Damaged, Repair and paint (complete)



Seat cover FL, Hole, Replace



Wing RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Bonnet, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Paint



Door FR, Scratch(es), Paint




Sliding door R, Scratch(es), Paint



Wing RR, Scratch(es), Paint



Rear light R, Broken, Replace



Bumper R, Scratch(es), Paint



Tyres, No damage, Check

