



**PEUGEOT 508: 3440-LZK**

Vinnumber:	<b>VR3FBYHZTNY568447</b>	Versionname:	<b>5P Active Pack BlueHDi 130 S&amp;S EAT8 berlina con portón 96kW 5P automática</b>
First Registrationdate:	<b>26/07/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>121360</b>	Power Kw:	
Bodytype:	<b>Berline</b>	Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Diesel</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Central consol F
Number keys remote	<b>2</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	<b>Autom climate control</b>	

**Tyres**

<b>215/60/16/99 V</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>215/60 R 16 99 V</b>
Tyre size FR				<b>215/60 R 16 99 V</b>
Tyre size RL				<b>215/60 R 16 99 V</b>
Tyre size RR				<b>215/60 R 16 99 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

**Assistance equipment**


Repair kit	<b>No</b>
Interior, Dirty, Cleaning	



Service book, Missing, Repair/replace (lump sum)



User's manual, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Outer sill L, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Door FR, Dent(s), Acceptable



Door RR, Scratch(es), Repair and paint (complete)



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

