Ford Transit Custom 130PK Refrigerated Koelwagen L2H1 Airco Cruise Parkeersensoren v+a Euro6 L...

WF0YXXTTGYJU44519 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	wf0yxxttgyju44519
First Registration	1/11/2019
Country of Origin	France
Mileage	389,104 km
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	
Vehicle location	
Engine Output HP/PK	130 hp
Emission norm	Euro 6
Engine Type	YMF6
Power type	Diesel
Cilinder Amount	4
Distribution type	Belt
Engine displacement (cc)	1995
Amount of Axles	2
Undercarriage	Wheeled
Type of suspension axle 2	parabolic
Tyre condition Axle 1 Left (MM)	3 mm
Tyre condition Axle 1 Right (M...	3 mm
Tyre condition Axle 2 Left (MM)	7 mm
Tyre condition Axle 2 Right (M...	7 mm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Tyre size Axle 1	215/65 R16
Tyre Size Axle 2	215/65 R16
Wheelbase	330 cm
Cooling engine build year	2018
Cooling engine brand	2026-11-03
Cooling engine power plug Ty...	230 V
Cooling engine type	Usky Tri-Temp V362
Type Lights	Halogen
Door opening height	117 cm
Door opening width	123 cm
Inner height	123 cm
Inner length	145 cm
Inner width	148 cm
Space between wheelarches	123 cm
Van size	L2H1
Superstructure brand	Gruau
Superstructure build year	2018
Superstructure wall thickness	4.5 cm
Mileage	389104 km
Airco option	airco
Number of seats	3
Type of cabin	Single
Type of Radio	FM
Empty weight	2643 kg
Registration Date	2019-01-11
Towing weight	1965 kg
Gross Vehicle Weight (GVW)	3400 kg
VIN / Serial Number/ Chassisn...	WF0YXXTTGYJU44519
Brand	Ford
Model	Transit Custom
Product Group (Tax)	Refrigerated Closed Van
Type extended	Transit Custom 130PK
Axle capacity 1	1750 kg
Axle configuration	2002-10-04
Colour	white
Country of origin	FR
Type of drive	FWD
Max load capacity	757 kg
Vehicle Height (cm)	234 cm
Vehicle Length (cm)	540 cm
Vehicle Width (cm)	198 cm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Transmission	Manual
Amount of forward gears	6
Truck ID	70330155
Lot	51
First registration	January 11, 2019
November 10, 2026 at 02	25 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

4 damages reported | Worst: Minor



Multiple — Minor
Cosmetic Damage
Exterior damages



Windshield — Minor
Crack
The windshield has a crack.



Engine Bay — Minor
Leakage
oil stain along the edge of the oil pan

Unknown — Minor
Other
The air conditioning is not working



Front / Right



Back / Left




R 1 3 5
2 4 6


OFF


A/C
MAX A/C
MAX


FM 2 9:34
107.10 MHz
VOL
OK
TUNE
1
2
3
4
5
6


SET+
CAN
RES
LIM
SET-


Ford
OK






ASCON TECNOLOGIC
Y39E
KR1






12V


Snelh.meter 25°
Brandstofpeil laag
Rijbereik: 66 km
389108 km
rpm x1000
km/h
°C
1/2






SINEWAVE INVERTER-CHARGER
Sinewave inverter-charger
SINEWAVE INVERTER-CHARGER
Sinewave inverter-charger
Manuel, Gebruikersaanwijzing, Benutzerhandbuch, Manuel Utilisateur, Manual Para Utilizador
Please read this manual before operating your inverter-charger
FORD TRANSIT CUSTOM Guide rapide
Sommaire



































FM 2 9:34
107.10 MHz
VOL
OK
TUNE
1
2
3
4
5
6


Ford
OK






12V


Snelheidsmeter 25°
Brandstofpeil laag
Rijbereik: 66 km
999106 km
0
1
2
3
4
5
6
20
40
60
80
100
120
140
160
180
200


Isberg
Gruau
9 bd Marius et René GRUAU
C.S. 24209
53942 St Berthevin Cedex
FRANCE
Tél. : 02.43.66.39.00
Type / Modèle : ISO -
PV de référence :
N° de série :
date :
MM / AAAA

