

INSPECTION REPORT

End of contract

GENERAL INFO

File	308741
License plate	2ATE493
Vehicle identification number	W1K1183861N236364
Dossier	2021 027 135
Make	Mercedes CLA 250 e Aut.
Mileage	64116
First registration	07/07/2021
client availability date	27/03/2026
inspectionDate	25/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
40	Windshield // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Damage within Renta-norm-



Windshield // Repair-glass damage



Interior / Side Cover rear Seat / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Polish-scratch



Door Rear Right // Polish-scratch