



## Peugeot 3008: 2ANV939

Vinnnumber:	<b>VF3MCYHZUMS064745</b>	Versionname:	
First Registrationdate:	<b>28/05/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>122602</b>	Power Kw:	
Bodytype:		Body colour	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted)	<b>Aluminium</b>
Transmission:	<b>Front</b>		
Fueltype:	<b>Diesel</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Certificate of Conformity	<b>Yes</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Car (BE)	<b>Yes</b>		
Registration Certificate Home (BE)	<b>No</b>		

## Options

Number of keys total	<b>2</b>	Front parking sensors	
Number keys remote	<b>2</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		
Type of radio	<b>Multimedia</b>		
Type of GPS storage	<b>HD</b>		

## Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	<b>Dunlop: 5 mm</b>	Fr.R.	<b>Dunlop: 5 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>225/55 R 18 102 V</b>
Tyre size FR				<b>225/55 R 18 102 V</b>
Tyre size RL				<b>225/55 R 18 102 V</b>
Tyre size RR				<b>225/55 R 18 102 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>257</b>
Tyre make FR				<b>257</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Seat cover FL, Worn, Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Smart repair



Alloy rim RL polished, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Luggage compartment cover, Missing, Replace



Wing RR, Dent(s), Paintless dent repair



Bodywork, Not original part, Sticker removal



Roof, Dent(s), Acceptable

