



Expertise

Protocol number: 46825015
Order No. / Reference: 26671254
Inspection date: 28 Jul 2026

Manufacturer: Mazda

Model: 2 SKYACTIV G 90 M HYBRID Homura

VIN: JMZDJ6HC601452321



Vehicle details

Manufacturer / Type / Model / Equipment

Mazda 2 SKYACTIV G 90 M HYBRID Homura

Vehicle Identification number	JMZDJ6HC601452321
Mileage (Read)	9,886 km
First registration	7 Jun 2023
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	

Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,496 ccm / 4
Power	66 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Deep Crystal Blue Mica
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	19,688 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HH046334
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7118 / AIO 00040		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,540 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/65 R15 88T	Winter tyres on Steel	Falken	6mm / 6mm
2)	185/65 R15 88T	Winter tyres on Steel	Falken	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	6mm / 6mm
2)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Front airbag (side airbags)
- Airbag head/shoulder airbags front and rear
- Anti-lock braking system (with electronic brake force distribution (EBD) and brake assist (EBA))
- Electrically folding exterior mirrors (automatically when the door is locked)
- Exterior mirror caps in black
- Third brake light (mounted high)
- Tinted glazing (heat-insulating)
- Coming/leaving home light function
- Roof spoiler in car color
- Dynamic Stability Control (DSC) with Traction Control System (TCS)
- Wheels: 16" alloy wheels in black (185/60 R16 Toyo Tires Proxes R55A tires)
- Electric windows, front and rear (with comfort function for the driver's window)
- Luggage compartment cover
- Transmission: 6-speed manual transmission
- Rear window wiper
- Automatic air conditioning
- Headrests (rear (3), height adjustable)
- Radiator grille honeycomb radiator grille
- Steering wheel: Leather steering wheel, leather gearshift knob and handbrake lever
- Steering wheel heating
- Reading lamps (front (2))
- Red air vent rings
- Makeup mirrors for driver and front passenger
- Engine start/stop button
- Emergency Stop Signaling (ESS)
- Package: CONVENIENCE PACKAGE (Rear Parking Assist (RCTA) - City Brake Support (SCBS F) with pedestrian detection - Rear parking sensors - Automatic climate control - Light and rain sensor - Heated seats for driver and front passenger - Blind Spot Monitoring (BSM))
- Radio accessories: Android Auto and Wireless Apple CarPlay
- Radio accessories: Hands-free system with voice control and Bluetooth audio streaming
- Rear view camera
- Rear side windows and rear window tinted
- Electric power steering
- Seats: Passenger seat height adjustable
- Seats: Driver's seat height adjustable
- Seats: ISOFIX child seat anchors (on the outer rear seats)
- Seats: Heated seats for driver and front passenger
- Lane Change Assist Plus (BSM)
- Exterior door handles painted in car color
- Full LED headlights with LED light signature
- Electronic immobilizer
- Airbag for driver and front passenger (passenger airbag, deactivatable)
- Rear Cross Traffic Alert (RCTA)
- Heated exterior mirrors
- Electrically adjustable exterior mirrors (with integrated side indicators)
- Hill Start Assist (HLA)
- Smart City Brake Support (SCBS) (with pedestrian detection)
- Shark Fin roof antenna
- Digital tachometer, analog speedometer
- Rear parking sensors
- Driving dynamics control: G-Vectoring Control Plus GVC (Optimized steering precision and higher driving dynamics, less steering effort and fatigue, more natural and comfortable driving behavior for all passengers thanks to reduced centrifugal forces)
- Cruise control system with speed limiter (Cruisematic)
- Back window, heater
- i-stop: Intelligent Mazda engine stop/start system
- Comfort turn signal function
- Headrests (front height adjustable)
- LED daytime running lights
- Steering wheel: Steering wheel control buttons for audio source and volume (hands-free system and cruise control)
- Steering column adjustable in height and length
- Light sensor
- M-Hybrid System
- Mobility kit (compressor and tire sealant)
- Multi-information display (with outside temperature display and touring computer)
- Upholstery: Cloth
- Radio: Mazda audio system with radio (20.3 cm (8 inch) color display, high resolution, usable as a touchscreen when the vehicle is stationary - Multi Commander for convenient and safe operation - Digital radio tuner (DAB+) - two USB ports and AUX port - Internet radio application: via the aha and Stitcher apps - 6 speakers)
- Rain sensor
- Tire pressure monitoring system (indirectly via ABS)
- Rear seat backrest asymmetrically split and foldable (60:40)
- Seat belts: 3-point automatic seat belts for all seats (front with height adjustment - belt tensioners with belt force limiter, front and rear - warning light and sound for unfastened seat belts)
- Lane Keeping Assist - Active with Steering Support (LAS) (Warns the driver of an unintentional lane change and can also intervene by actively steering to guide the vehicle back into the lane.)
- Central locking with remote control



Extra equipment

- Paint finish: Metallic
- winter tires
- Navigation: Mazda SD navigation system (3D map display, high resolution - destination input via contact data from a smartphone possible - expandable with online services (fee applies) - arrow navigation additionally in the head-up display (optional with Sports-Line))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Cover - Scratched - Smart repair
2	Front bumper	Front bumper - Scratched - Cover / polish
3	Door - front left side	Door - Scratched - Cover / polish
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres




Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.






Figure 29: Misc.



Damage 1: Instrument panel: Cover - Scratched - Smart repair




Damage 1: Instrument panel: Cover - Scratched - Smart repair



Damage 2: Front bumper: Front bumper - Scratched - Cover / polish



Damage 2: Front bumper: Front bumper - Scratched - Cover / polish



Damage 3: Door - front left side: Door - Scratched - Cover / polish



Damage 3: Door - front left side: Door - Scratched - Cover / polish



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint