

Volkswagen TRANSPORTER 2.0 TDI DC 102pk L2H1 Comfortline Trekhaak, Jun-19, 142,602 km



Memo



VIN	WV1ZZZ7HZKH127094
Initial registration	27-06-2019
Initial Dutch Registration	27-06-2019
European Type Approval	e1*2007/46*0130*30
Mileage reading / hour counter reading	142,602 km 
Mileage Status:	Logical (NAP)
Automatic	No
Fuel	Diesel
Cylinders / Engine capacity	4 / 1968
Weight	1854 kg
Doors	5
Power capacity	75 kW
Emission code / Energy label	6
Wheelbase	340
Loading space	
Load capacity	946
RDW details	
Battery capacity	
Range	
Battery health	
Charging cables type	
AC/DC	
Battery purchase/rent	Unknown
Taxation	VAT (Grey number plate)
Colour	n/a
Country of registration	The Netherlands
Origin	Lease
Indicative catalog price	

Accessories fitted to vehicles

 Manually operated air conditioning	 Cruise control	 Start immobiliser
 ABS	 Electronic Stability Program	 Tow bar
 Automatic interior mirror dimmer	 Electric windows front	 Heated windscreen
 Bluetooth telephone connection	 Parking sensors rear	
 Central locking remote control	 Sliding door right	

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|-----------------------------|--------------------------|----------------------------|
| • Achterklep | • Comfortstoel(en) | • Multimedia-voorbereiding |
| • Airco | • Cruise control | • Passagiersairbag |
| • Armsteun voor | • Dimlichten aut. | • Start/stop systeem |
| • Bestuursdairbag | • ESD | • Vermoeidheids herkenning |
| • Bluetooth telefoonvoorb. | • ESP | • Verstelbaar stuur |
| • Boordcomputer | • Hill hold functie | • Verwarmde voorruit |
| • Buitensp. elektr. + verw. | • Mistlampen v. adaptief | • Zijschuifdeur rechts |



Comments

No remarks

Vehicle state

MOT due date	14-02-2027	Cambelt replaced	Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys 2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium Not present	Charging cable for plug connection	Not present
		Vehicle location On location Owner	Wheel locks	Not present



Tyres

Rim size	16"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	All Season tyre	5 mm
Front wheel right	Continental	All Season tyre	5 mm
Rear wheel left	Continental	All Season tyre	7 mm
Rear wheel right	Continental	All Season tyre	6 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
Unacceptable damage		
1	A-stijl I bekleding binnen	Gat
2	Front wing left	scratch(es)
3	Rear wing left	distorted
4	Dorpel I	distorted
5	Front door left	scratch(es)
6	Bumper v bekleding	Gebroken
7	Front screen	stone impact
8	Rear wing right	distorted
9	Schuifdeur r	distorted
10	Rear door left	distorted

11



Koetswerk

Niet origineel

Comments

No remarks