



Audi A3 (UKL): 2BXQ418

Vinnumber:	WAUZZZGY2NA074015	Versionname:	A3 Berline S-Line 35 1.5TFSi 150pk/cv 4p S-Tronic
First Registrationdate:	2/05/2022	Fiscalpower:	
Expertise Mileage:	114329	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	dans 12000km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/17/94 Y				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 94 Y
Tyre size FR				225/45 R 17 94 Y
Tyre size RL				225/45 R 17 94 Y
Tyre size RR				225/45 R 17 94 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Engine insulation, Tear, Replace



Bumper F, Scratch(es), Spot repair



Alloy rim FL, Scratch(es), Replace



Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)





Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Kenteken	2BXQ418
Merk Model	Audi A3 Berline S-Line 35 1.5TFSi 150pk/cv 4p S-Tronic
Brandstofsoort	Benzine
Datum deel1	5/2/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
1/22/26	96,248	batterij	Vervangen
1/22/26	96,248	klein materiaal	
1/22/26	96,248	koelwatervloeistof	Bijvullen/-laden
1/22/26	96,248	luchtfilter	Vervangen
1/22/26	96,248	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
1/22/26	96,248	ruitenswisserrubber vooraan	Vervangen
1/22/26	96,248	ruitenswisservloeistof	Bijvullen/-laden
9/4/25	84,899	batterij	Vervangen
9/4/25	84,899	klein materiaal	
8/13/24	61,210	batterij	Vervangen
8/13/24	61,210	bougie	Vervangen
8/13/24	61,210	klein materiaal	
8/13/24	61,210	luchtfilter interieur	Vervangen
8/13/24	61,210	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
8/13/24	61,210	remvloeistof	Vervangen
6/16/23	30,000	klein materiaal	Uitvoeren
6/16/23	30,000	koelwatervloeistof	Vervangen
6/16/23	30,000	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/16/23	30,000	ruitenswisservloeistof	Bijvullen/-laden