MACADAM








Peugeot 2008 (UKL): 2CER616

Vinnumber:	**VR3USHNKKNJ659995**	Versionname:	**2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p**
First Registrationdate:	**27/06/2022**	Fiscalpower:	
Expertise Mileage:	**83178**	Power Kw:	**74**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**over 11400 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Continental: 3 mm**	Fr.R.	**Continental: 3 mm**
	Re.L.	**Continental: 3 mm**	Re.R.	**Continental: 3 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**


Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Backrest cover FL, Damaged, Acceptable




Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable










Door FL, Dent(s), Acceptable




Outside rear-view mirror housing L, Scratch(es), Acceptable




Alloy rim RL, Scratch(es), Acceptable






Internal boot lining L, Scratch(es), Acceptable




Internal boot lining R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Tailgate / Boot, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Repair and paint (complete)





Wing FR, Scratch(es), Acceptable




Roof, Dent(s) and scratch(es), Acceptable








Onderhoudshistorie van: VR3USHNKKNJ659995

ALPHABET

Kenteken	2CER616
Merk Model	Peugeot 2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/27/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/7/26	74,673	75000 km	Uitvoeren
5/7/26	74,673	bougie	Vervangen
5/7/26	74,673	diagnose	Uitvoeren
5/7/26	74,673	luchtfilter	Vervangen
5/7/26	74,673	luchtfilter interieur	Vervangen
5/7/26	74,673	oliezeef	Vervangen
5/7/26	74,673	ruitenwisserrubber achter	Vervangen
5/7/26	74,673	ruitenwisserrubber vooraan	Vervangen
10/13/25	64,547	distributieriem	Vervangen
10/13/25	64,547	foutencodes uitlezen	Uitvoeren
8/29/25	61,368	60000 km	Uitvoeren
8/29/25	61,368	oliezeef	Vervangen
4/1/25	52,604	halogeenlamp	Vervangen
9/16/24	39,869	40000 km	Uitvoeren
9/16/24	39,869	bougie	Vervangen
9/16/24	39,869	luchtfilter	Vervangen
9/16/24	39,869	luchtfilter interieur	Vervangen
9/16/24	39,869	oliezeef	Vervangen
9/16/24	39,869	remvloeistof	Bijvullen/-laden
8/2/23	19,978	20000 km	Uitvoeren
8/2/23	19,978	luchtfilter interieur	Vervangen
8/2/23	19,978	oliezeef	Vervangen