





Audi			
Vinn	WAUZZZGYXNA036693		Versionname:
First Registrationdate:	3/01/2022		Fiscalpower:
Expertise Mileage:	104855		Power Kw:
Bodytype:			Body colour
Gearbox:	Automatic		Type of rims (mounted)
Transmission:			Parking lot
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Winter tyres:	205/55/16/92 H		
	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			205/55 R 16 92 H
Tyre size FR			205/55 R 16 92 H
Tyre size RL			205/55 R 16 92 H
Tyre size RR			205/55 R 16 92 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2137,35
Bumper F, Scratch(es), Repair and paint (complete)			296,58



Bonnet, Bad repair, Repair and paint (complete)	406,19
---	--------



Wing RL, Chemical polution, Polish	0,00
------------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------



Rear window, Scratch(es), Replace	285,65
-----------------------------------	--------



Tailgate / Boot, Chemical polution, Spot repair	148,33
---	--------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------



Roof, Chemical polution, Repair and paint (complete)	704,02
--	--------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

