MACADAM








BMW 2 Reeks Active Tourer (UKL): 1YXJ686

Vinnumber:	**WBA6T510507H64642**	Versionname:	**216d Active Tourer (F45) 1.5d 116pk/cv 5p**
First Registrationdate:	**21/01/2021**	Fiscalpower:	
Expertise Mileage:	**140990**	Power Kw:	**85**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**8000.0**		
Maintenance	**januari 2028**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/60/16/92 H**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Michelin: 5 mm**
	Re.L.	**Michelin: 4 mm**	Re.R.	**Michelin: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/60 R 16 92 H**
Tyre size FR	**205/60 R 16 92 H**
Tyre size RL	**205/60 R 16 96 W**
Tyre size RR	**205/60 R 16 96 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Gear shift lever knob, Broken, Replace




Steering wheel, Worn, Acceptable





Seat cover FL, Stain, Acceptable




Backrest cover FL, Scratch(es), Acceptable





Backrest cover FR, Scratch(es), Acceptable




Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Windscreen, Stone chip(s), Windscreen repair




Door FL, Dent(s) and scratch(es), Acceptable





Door RL, Scratch(es), Acceptable






Alloy rim RL, Scratch(es), Acceptable




Wing RL, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable





Bumper R, Dent(s) and scratch(es), Repair and paint (complete)












Door FR, Scratch(es), Acceptable






Wing FR, Dent(s) and scratch(es), Repair and paint (complete)






Bodywork, Paint measurement, Acceptable

