MACADAM










FORD TRANSIT CUSTOM: GP-799-FY

Vinnumber:	**WF0YXXTTGYPE31382**	Versionname:	**FORD TRANSIT CUSTOM 2.0 ECOBLUE 170 280 L1H1 AUTO TREND BUS VU [4P] bva 6-170CH-7cv (fourgon tÃ´lÃ©simple cabine)**
First Registrationdate:	**31/05/2023**	Fiscalpower:	
Expertise Mileage:	**68753**	Power Kw:	**125**
Bodytype:	**Transporter**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**215/65/16/109 T**			
	Fr.L.	**Kleber: 45%**	Fr.R.	**Kleber: 50%**
	Re.L.	**Michelin: 55%**	Re.R.	**Michelin: 60%**

Tyre profile depth FL	**5.2**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.6**
Tyre profile depth RR	**4.3**
Tyre size FL	**215/65 R 16 109 T**
Tyre size FR	**215/65 R 16 109 T**
Tyre size RL	**215/65 R 16 109 T**
Tyre size RR	**215/65 R 16 109 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2479**
Tyre make FR	**2479**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Spare wheel	**Yes**	Jack	**No**

Malfunction indicator, Blinking, Check




Remote ignition key, Missing, Repair/replace (lump sum)




Seat cover FL, Tear, Replace





Wheel cover FL, Missing, Replace





Wheel cover RR, Missing, Replace





Wheel cover FR, Missing, Replace





Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)







Bumper moulding F, Scratch(es), Paint






Sliding door R, Scratch(es), Paint






Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)







Outside rear-view mirror housing R, Scratch(es), Paint





Boot door panel RL, Scratch(es), Paint





Bumper corner RR, Crack, Repair and paint (complete)






Boot door panel RR, Dent(s), Acceptable





Jack, Missing, Repair/replace (lump sum)

