

INSPECTION REPORT


End of contract

GENERAL INFO

File	315400
License plate	2ANT959
Vehicle identification number	WBY7X41030SZ89799
Dossier	2020 357 006
Make	BMW iX3 sDrive35
Mileage	120265
First registration	27/05/2021
client availability date	19/06/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
76	Side View Mirror Left / Shell / Replace Painted	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
101	Door Rear Left // Smart Repair Medium	N
107	Door Rear Left / Trim / Replace	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	Y
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	Y
202	Rocker Panel Right // Painting	Y
236	Wing Front right // Polish	Y
283	Bumper Rear / Trim Right / Replace	Y
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Front Left / Trim / Replace-scratch




Rear Bonnet // Polish-scratch



Rocker Panel Right // Painting-scratch




Wing Front right // Polish-scratch



Side View Mirror Left / Shell / Replace Painted-scratch



Wing Rear Left // Polish-scratch





Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Seat Front Left // Repair-scratch



Seat Front Right // Repair-scratch



Door Front Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Bumper Rear / Trim Right / Replace-scratch + dent



Door Rear Left // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Rear Left / Trim / Replace-Chipped paint



Door Rear Right / Trim / Replace-Chipped paint