



VOLKSWAGEN TRANSPORTER: FW-865-HQ

Vinnumber:	WV1ZZZ7HZMH025179	Versionname:	VOLKSWAGEN TRANSPORTER 2.0 TDi 150 4MO L2H1 Business Line VU [4P] bvm 6-150CH-7cv (fourgon tÅ¹IA@simple cabine)
First Registrationdate:	6/01/2021	Fiscalpower:	
Expertise Mileage:	189681	Power Kw:	110
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

205/65/16/107 T				
Summer tyres:	Fr.L.	Continental: 35%	Fr.R.	Continental: 25%
	Re.L.	Continental: 10%	Re.R.	Hankook: 45%
Tyre profile depth FL				5.9
Tyre profile depth FR				6.5
Tyre profile depth RL				7.6
Tyre profile depth RR				5.2
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 T
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				260

Assistance equipment

Spare wheel	No	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Malfunction indicator, Blinking, Check



Dashboard, Scratch(es), Replace



Door seal RR, Tear, Replace



Wheel cover FR, Missing, Replace



Tyre RR, Out of tolerance, Replace



Wheel cover FL, Missing, Replace



Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Supplementary brake light, Broken, Replace



Spare rim, Missing, Replace



Spare tyre, Missing, Replace



Boot lid covering R, Broken, Replace



Bodywork, Not original part, Remove lettering



Load compartment roof, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: **FW-865-HQ** Date de 1ère immatriculation: **06/01/2021**

Modèle: **Volkswagen TRANSPORTER 2.0 TDi 150 4MO L2H1 Business Line VU [4P] bvm 6-150CH-7cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
31/10/2025	170.840	LECLUSE AUTOMOBILES	PLAQUETTES AR RPLT
	0		MOYEU DE ROUE RPLT
	0		CARDAN AVG RPLT
	0		RECYCLAGE
	0		BV COMPLETE RPLT
	0		PLAQUETTES AV RPLT
	0		SERRURE DE PORTE ARD RPLT
17/09/2025	162.500	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
09/07/2025	156.191	VGRF GRAND OUEST	DISQUES PLAQUETTES AR RPLT
	0		DIVERS ELEC
	0		DIVERS ELEC
	0		SERRURE DE PORTE ARD RPLT
	0		DIAG
28/05/2025	154.185	VGRF GRAND OUEST	REVISION
	0		HUILE BV RPLT
	0		LIQUIDE DE FREIN
	0		RECYCLAGE
26/12/2024	140.677	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
19/08/2024	124.271	VGRF GRAND OUEST	DISQUES PLAQUETTES AV RPLT
	0		ADBLUE
	0		BALAISSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE LAVE GLACE
	0		RECYCLAGE
27/11/2023	93.033	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
15/09/2023	85.548	VGRF GRAND OUEST	HUILE BV RPLT
	0		BALAISSUIE GLACE AV
	0		LIQUIDE LAVE GLACE
	0		LIQUIDE DE FREIN
	0		REVISION
	0		RECYCLAGE

Historique Maintenance

Immatriculation: **FW-865-HQ**

Date de 1ère immatriculation: **06/01/2021**

Modèle: **Volkswagen TRANSPORTER 2.0 TDi 150 4MO L2H1 Business Line VU [4P] bvm 6-150CH-7cv
(fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
31/08/2023	83.315	VGRF GRAND OUEST	DIVERS ELEC
23/08/2023	83.315	VGRF GRAND OUEST	DISQUES PLAQUETTES AR RPLT
	0		RECYCLAGE
	0		PLAQUETTES AV RPLT
	0		LAMPE AR RPLT
19/04/2022	42.430	UTILITAIRES SERVICES	REVISION
20/01/2022	32.206	PROFIL PLUS	REMPLACEMENT PNEUS ETE