MACADAM











BMW 3 Reeks (KKL): 2BPP931

Vinnumber:	**WBA6N91040FM50985**	Versionname:	**320e Touring (G21) 2.0i 204pk/cv 4p**
First Registrationdate:	**7/02/2022**	Fiscalpower:	
Expertise Mileage:	**161500**	Power Kw:	**120**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**+ 6000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**225/50/17/98 H**			
	Fr.L.	**Firestone: 6 mm**	Fr.R.	**Firestone: 6 mm**
	Re.L.	**Firestone: 6 mm**	Re.R.	**Firestone: 5 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/50 R 17 98 H**
Tyre size FR	**225/50 R 17 98 H**
Tyre size RL	**225/50 R 17 98 H**
Tyre size RR	**225/50 R 17 98 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**258**
Tyre make RR	**258**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**

Alloy rim RL, Scratch(es), Acceptable





Wing RL, Repaired, Check




Door FL, Repaired, Check




Bumper R, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable




Bodywork, Not original part, Remove lettering




Bodywork, Paint measurement, Check



Onderhoudshistorie van: WBA6N91040FM50985

ALPHABET

Kenteken	2BPP931
Merk Model	BMW 320e Touring (G21) 2.0i 204pk/cv 4p
Brandstofsoort	Benzine
Datum deel1	2/7/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/30/26	160,674	diagnose	Uitvoeren
7/23/26	157,103	diagnose	Uitvoeren
7/23/26	157,103	klein materiaal	
11/3/25	133,580	batterij	Vervangen
11/3/25	133,580	BMW/MINI service standaard omvang	Uitvoeren
11/3/25	133,580	BMW/MINI service voertuig-check	Uitvoeren
11/3/25	133,580	bougie	Vervangen
11/3/25	133,580	klein materiaal	
11/3/25	133,580	koelwatervloeistof	Bijvullen/-laden
11/3/25	133,580	ruitenwisservloeistof	Bijvullen/-laden
11/3/25	133,580	service luchtfilter	Uitvoeren
11/3/25	133,580	service microfilter	Uitvoeren
11/3/25	133,580	service motorolie	Uitvoeren
5/16/25	115,208	BMW/MINI service standaard omvang	Uitvoeren
5/16/25	115,208	klein materiaal	
5/16/25	115,208	remblokken achter	Vervangen
1/10/25	100,833	batterij	Vervangen
1/10/25	100,833	BMW/MINI service standaard omvang	Uitvoeren
1/10/25	100,833	klein materiaal	
1/10/25	100,833	remvloeistof	Vervangen
1/10/25	100,833	ruitenwisserrubber achter	Vervangen
1/10/25	100,833	ruitenwisserrubber vooraan	Vervangen
1/10/25	100,833	service microfilter	Uitvoeren
1/10/25	100,833	service motorolie	Uitvoeren
4/5/24	66,354	batterij	Vervangen
4/5/24	66,354	BMW/MINI service standaard omvang	Uitvoeren
4/5/24	66,354	BMW/MINI service voertuig-check	Uitvoeren
4/5/24	66,354	bougie	Vervangen
4/5/24	66,354	klein materiaal	Uitvoeren
4/5/24	66,354	service luchtfilter	Uitvoeren
4/5/24	66,354	service microfilter	Uitvoeren
4/5/24	66,354	service motorolie	Uitvoeren
12/27/22	31,395	batterij	Vervangen
12/27/22	31,395	service microfilter	Uitvoeren
12/27/22	31,395	service motorolie	Uitvoeren
10/26/22	25,005	controle niveaus	Uitvoeren
6/23/22	11,151	uitlijnen wielen voor en achter	Afstellen