



Volvo V90: P467RF

Vinnumber:	YV1PWH1VDN1182539	Versionname:	V90 2.0 T6 Recharge 257kW AWD Inscription automaat
First Registrationdate:	20/05/2022	Fiscalpower:	
Expertise Mileage:	180001	Power Kw:	186
Bodytype:		Body colour	Platinum Grey metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	1165
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining leather
GPS		Sun Roof electric
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors
		Hook
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 18 / 100 / V / Aluminium	5,3 mm	Hankook	Winter
	Right	245 / 45 / 18 / 100 / V / Aluminium	6,0 mm	Hankook	Winter
Rear	Left	245 / 45 / 18 / 100 / V / Aluminium	4,8 mm	Hankook	Winter
	Right	245 / 45 / 18 / 100 / V / Aluminium	5,0 mm	Hankook	Winter

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Service, Maintenance, Execute



Seat cover FL, Tear, Replace



Interior, Dirty, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Replace and paint



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Chemical polution, Polish





Kenteken	P467RF
Merk Model	Volvo V90 2.0 T6 Recharge 257kW AWD Inscription automaat
Brandstofsoort	Benzine
Datum deel1	20-05-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
31-03-26	175.760	APK
31-03-26	175.760	Controle beurt
31-03-26	175.760	Volvo Check aandrijving
25-08-25	151.229	Afstandsbediening
01-07-25	144.151	Onderhoudsbeurt
01-07-25	144.151	Remvloeistof
01-07-25	144.151	Volvo Check slijtagedelen
03-12-24	119.313	Bougie
03-12-24	119.313	Luchtfilter
03-12-24	119.313	Onderhoudsbeurt
03-12-24	119.313	Volvo Check aandrijving
03-12-24	119.313	Volvo Check slijtagedelen
15-10-24	111.920	LCD display
17-06-24	95.128	Onderhoudsbeurt
17-06-24	95.128	Remvloeistof
17-06-24	95.128	Ruitenwischerblad(en) voorzijde
17-06-24	95.128	Volvo Check slijtagedelen
08-11-23	65.027	Bougie
08-11-23	65.027	Luchtfilter
08-11-23	65.027	Onderhoudsbeurt
08-11-23	65.027	Ruitenwischerblad(en) voorzijde
08-11-23	65.027	Volvo Check aandrijving
08-11-23	65.027	Volvo Check slijtagedelen
25-01-23	32.324	Onderhoudsbeurt
25-01-23	32.324	Ruitenwischerblad(en) voorzijde
25-01-23	32.324	Volvo Check slijtagedelen