



Peugeot 208: P381VJ

Vinnumber:	VR3UHZKXZNT054853	Versionname:	e-208 50kWh 100kW Active Pack automaat
First Registrationdate:	22/06/2022	Fiscalpower:	
Expertise Mileage:	51531	Power Kw:	100
Bodytype:		Body colour	Jaune Faro metaallak
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	358
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Aluminium	5,8 mm	Michelin	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	5,8 mm	Michelin	Summer
Rear	Left	195 / 55 / 16 / 87 / H / Aluminium	6,4 mm	Michelin	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	6,2 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	---

Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)




Bonnet, Chemical polution, Polish



Wing RR, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish



Kenteken	P381VJ
Merk Model	Peugeot e-208 50kWh 100kW Active Pack automaat
Brandstofsoort	Elektrisch
Datum deel1	22-06-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
12-05-26	48.624	APK
12-05-26	48.624	Vervanging band
06-02-26	42.642	APK
06-02-26	42.642	Koelvloeistof High Voltage accu
06-02-26	42.642	Onderhoudsbeurt
06-02-26	42.642	Remvloeistof
06-02-26	42.642	Ruitenwisserblad(en) voorzijde
30-04-25	34.032	Airco controle
30-04-25	34.032	Airo vulling
14-04-25	33.912	Remblokken achterzijde
07-03-24	24.018	Airco pomp
07-03-24	24.018	Onderhoudsbeurt
07-03-24	24.018	Remvloeistof
23-02-23	12.206	Onderhoudsbeurt
24-01-23	0	Accu