



IDENTIFICATION VEHICLE

Driver name:
Make: BMW
Model / version: X1
Vin: WBA31AC0305V35982
Plate:
Mileage: 221107
First registration: 04/05/2022
Color: Saphirschwar


ADDITIONAL INFORMATION





Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
7 rapports
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 225
Accoudoir central avant
1.50 litre
Métallisée vernissée
Rétroviseurs rabattables électriques

Sièges avant chauffants
Volant sport
Aide au stationnement arrière
Régulateur automatique de la distance
Lunette arrière teintée foncée
Toit ouvrant électrique
Protection piéton

Contrôle pression des pneus
mesures CO2 étendues
Connected Drive Services

Système navigation
Equipement Advantage
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 55
Indice de vitesse arrière H
Climatisation automatique
Diesel
85 kw
Rétroviseur gauche chauffant
Rétroviseur intérieur jour/nuit
automatique
Garnitures simili-cuir
Volant multifonction
Assistance au parking
Ouverture du coffre électriquement
Vitres portes arrière teintées foncées
Toit ouvrant vitré panoramique
Freinage d'urgence assistée autonome
(urbain)
depuis 03.22
Teleservices
sièges ar réglables

Transmission automatique
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 225
Climatisation réfrigérant 1234YF
1496 cm3
115 ch
Rétroviseur droit chauffant
Siège avant gauche chauffant
Volant cuir
Aide au stationnement avant
Caméra avant
Appel de secours
Vitres de custode teintées foncées
Fixotoit noir
Avertisseur de collision avant
réservoir carburant de grande capacité
tuner DAB
pack de rangement

filet de séparation coffre

boulons antivol de roue

encarts intérieurs noir brillant avec accents en chrome perlé brillant

spécifique Europe

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✖	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✖
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm		225/55R17 97H	Winter		?
Front right	4 mm		225/55R17 97H	Winter		?
Rear left	4 mm		225/55R17 97H	Winter		?
Rear right	4 mm		225/55R17 97H	Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot cover	Grooved
2	Contact key - Boordcomputer resetten	Not original part
4	Alloy rim FL	Grooved
5	Door FL	Dent(s)
6	Wing RL	Dent(s) and scratch(es)
7	Door RL	Scratch(es)
8	Bumper R	Grooved
9	Wing RR	Dent(s)
10	Door FR	Grooved
11	Interior - Ozonreiniging wegens geurhinder	Dirty

Total: 10

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Dent(s) and scratch(es)	✓	✖	✖

Total: 1


DAMAGES DETAILS

1 - Boot cover - Grooved






2 - Contact key - Boordcomputer resetten - Not original part



4 - Alloy rim FL - Grooved



5 - Door FL - Dent(s)



6 - Wing RL - Dent(s) and scratch(es)



7 - Door RL - Scratch(es)



8 - Bumper R - Grooved



9 - Wing RR - Dent(s)



10 - Door FR - Grooved



11 - Interior - Ozonreiniging wegens geurhinder - Dirty



3 - Bodywork - Dent(s) and scratch(es) - Renta®



Expert

04/09/2026 11:50

CV