MACADAM








RENAULT EXPRESS: 9651-MCF

Vinnumber:	**VF1RJK00270098893**	Versionname:	**Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual**
First Registrationdate:	**14/11/2022**	Fiscalpower:	
Expertise Mileage:	**125171**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/88 H**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**185/65 R 15 88 H**
Tyre size FR	**185/65 R 15 88 H**
Tyre size RL	**185/65 R 15 88 H**
Tyre size RR	**185/65 R 15 88 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Door panel FR, Scratch(es), Repair/replace (lump sum)




Seat cover FL, Tear, Repair/replace (lump sum)




Ignition key, Missing, Repair/replace (lump sum)




Outside rear-view mirror L, complete, Scratch(es), Paint




Outer door handle FL, Missing, Replace




Door FL, Scratch(es), Paint




Wing RL, Dent(s), Repair and paint (complete)




Bumper F, Scratch(es), Paint




Wing RR, Dent(s), Repair and paint (complete)




Sliding door R, Dent(s), Repair and paint (complete)




Door FR, Scratch(es), Paint




Outside rear-view mirror R, complete, Scratch(es), Paint




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)




Boot door panel RL, Scratch(es), Paint




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	9651-MCF
Modelo	Express	VIN	VF1RJK00270098893
Versión	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
08/09/2023	Paragolpes trasero, Pilotos, Portón trasero	8496	Talleres Estrenauto, S.l.
23/11/2023	Paragolpes trasero, Pilotos, Portón trasero	8496	Talleres Estrenauto, S.l.
26/03/2024	Puerta delantera derecha | Lampara Matricula, Revisión 2 años	20881	MORE AUTOMOCION S.L.
02/04/2024	Sustitución	20882	Futurwagen
08/08/2024	Sustitución	37295	JESUS ESTEBAN RUBIO
14/02/2025	varios	39585	NEW MOON PROJECT
03/09/2024	Rev. 30.000 kms	39585	TALLERES PEDRO MADROÑOS S.L.
22/11/2024	Varios general	46829	NEUMATICOS PALOMAR
09/04/2025	Pastillas delanteras	49597	AUTOSALAMANCA CARS
06/05/2025	Ecotasa - N2, Goodyear / 548157 - 185/65R15 88H EFFIGRIP PERF, Sustitucion y kit de montaje	53900	NEUPLASA S.L.
10/09/2025	Alineado sencillo, Ecotasa - N2, Goodyear / 542242 185/65X15 GYEAR.EFIG.PERF2 88H, Sustitucion y kit de montaje	73301	NEUMATICOS LUISCAR C.B.
12/09/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Filtro aceite, Filtro aire, Filtro antipolen - Nueva, Filtro combustible, Serv inspección 60000 KM, Sustituir Filtro aire, Sustituir	73969	AUTO SALAMANCA CARS S.L.

Fecha	Descripción	Kilómetros	Taller
	Filtro antipolen, Sustituir Filtro combustible, Tasa de gestión de aceites usados		
19/09/2025	Ecotasa - N2, Goodyear / 542242 185/65X15 GYEAR.EFIG.PERF2 88H, Sustitucion y kit de montaje	73975	NEUMATICOS LUISCAR C.B.
10/04/2026	Disco freno dl dr, Disco freno dl iz, Pastillas freno dl - Nueva, Sustituir Juego discos-pastillas dl / Sustituir Disco freno dl iz / Sustituir Disco freno dl dr	101318	AUTO SALAMANCA CARS S.L.
13/04/2026	Ecotasa - N2, Goodyear / 548157 - 185/65R15 88H EFFIGRIP PERF, Sustitucion y kit de montaje	101321	NEUPLASA S.L.
30/06/2026	Aceite motor - - - ALP 2, Arandela / tapón cárter, Filtro aceite, Filtro aire, Filtro antipolen - VALUE+ - Economic, Filtro combustible, Limpiar tambores freno, Serv inspección 120000 KM, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Filtro combustible, Tasa de gestión de aceites usados	112541	MOTOR PLASENCIA S.A.
10/08/2026	Alineado sencillo, Ecotasa - N2, Goodyear / 542242 185/65X15 GYEAR.EFIG.PERF2 88H, Sustitucion y kit de montaje	117840	NEUMATICOS LUISCAR C.B.