MACADAM









BMW X1: 2BHR228

Vinnumber:	**WBA31AC0005S72396**	Versionname:	
First Registrationdate:	**8/02/2021**	Fiscalpower:	
Expertise Mileage:	**153719**	Power Kw:	**85**
Bodytype:		Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**		
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**+ 17000 km**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Sun Roof electric	
Number keys remote	**2**	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Board Computer		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Roof bar black	
Steering wheel leather		Type of Tow bar	**Tow bar removable**
Type of headlighting	**Headlighting Halogen**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining leather**		
Type of climate control	**Autom climate control**		
Type of radio	**Multimedia**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/60/17/97 W**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 6 mm**
	Re.L.	**Bridgestone: 6 mm**	Re.R.	**Bridgestone: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**205/60 R 17 97 W**
Tyre size FR	**205/60 R 17 97 W**
Tyre size RL	**205/60 R 17 97 W**
Tyre size RR	**205/60 R 17 97 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**

Backrest cover FL, Broken, Forfeit




Seat cover FL, Burned, Replace




Bumper F, Scratch(es), Repair and paint (complete)






Door FL, Scratch(es), Acceptable




Door RL, Dent(s) and scratch(es), Acceptable






Alloy rim RL, Scratch(es), Repair and paint (complete)




Alloy rim FL, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Acceptable




Bumper R, Deformed / Strained, Repair and paint (complete)






Tailgate / Boot, Scratch(es), Acceptable




Wing RR, Dent(s), Paintless dent repair




Door RR, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Wing FR, Dent(s), Paintless dent repair




Alloy rim FR, Scratch(es), Repair and paint (complete)


