



CITROËN BERLINGO: ES-464-BD

Vinnumber:	VF77DBHW6HJ825042	Versionname:	CITROËN BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)
First Registrationdate:	16/11/2017	Fiscalpower:	
Expertise Mileage:	150890	Power Kw:	55
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	3		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	1	Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Type of climate control	Manual climate control		

Tyres

	195/70/15/102 T			
Summer tyres:	Fr.L.	Michelin: 5%	Fr.R.	Michelin: 5%
	Re.L.	Michelin: 0%	Re.R.	Michelin: 0%
Tyre profile depth FL				7.8
Tyre profile depth FR				7.7
Tyre profile depth RL				8.4
Tyre profile depth RR				8.2
Tyre size FL				195/70 R 15 102 T
Tyre size FR				195/70 R 15 102 T
Tyre size RL				195/70 R 15 102 T
Tyre size RR				195/70 R 15 102 T
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Seat cover FR, Stain, Cleaning			



Steering wheel, Worn, Acceptable



Outer sill L, Scratch(es), Paint



Side panel L, Dent(s) and scratch(es), Repair and paint (complete)



Central pillar moulding L, Deformed / Strained, Replace



Bumper F, Unclassped, Dismount/Mount



Wing RR, Scratch(es), Paint



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Deformed / Strained, Replace



Boot door panel RR, Scratch(es), Paint



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: ES-464-BD Date de 1ère immatriculation: 16/11/2017

Modèle: Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)

Date	Kilométrage	Fournisseur	Descriptif
10/06/2026	150.083	DEKRA AUTOMOTIVE TRAPPES	CONTRE VISITE CT
15/06/2026	149.972	COURTINE	BATTERIE RPLT
21/04/2026	149.908	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
05/09/2025	139.994	TACHARD AUTOMOBILE	PLAQUETTES AV RPLT
27/03/2025	130.655	DEKRA AUTOMOTIVE S.A	ANTIPOLLUTION
28/05/2025	128.864	COURTINE	REVISION ET CLIM ET AIR ET CARBURANT
			LAMPE CODE AVD RPLT
21/08/2024	114.348	COURTINE	COUPELLES AMORTISSEURS AV RPLT
			AMORTISSEURS AV RPLT
13/12/2023	114.001	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
27/11/2023	113.124	COURTINE	LAMPE CODE AVD RPLT
			REVISION ET CLIM
			DIVERS ECHAPPEMENT
			ECLAIRAGE DE PLAQUE RPLT
09/01/2023	101.650	COURTINE	FAP RPLT
			SONDE LAMBDA RPLT
05/05/2022	86.118	COURTINE	FILTRE A CARBURANT CTRL
			REVISION ET CLIM
27/12/2021	76.843	JACQUET AUTOMOBILES	INJECTEUR ADBLUE RPLT
22/11/2021	75.339	CONTROLE TECHNIQUE BRIDAL SARL	CONTROLE TECHNIQUE
22/10/2021	73.808	JACQUET AUTOMOBILES	ADBLUE
			REVISION
01/10/2020	56.787	JACQUET AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
			ADBLUE
			LIQUIDE DE FREIN
22/09/2020	56.251	JACQUET AUTOMOBILES	LAMPE CODE AVD RPLT
02/09/2020	54.274	JACQUET AUTOMOBILES	LAMPE CODE AVD RPLT
16/01/2020	40.543	JACQUET AUTOMOBILES	COMMANDE DE CLIM RPLT
			PLAQUETTES AV RPLT
30/09/2019	35.270	JACQUET AUTOMOBILES	LIQUIDE DE FREIN
			BALAIS ESSUIE GLACE AV
			REVISION ET CLIM

Historique Maintenance

Immatriculation: **ES-464-BD**

Date de 1ère immatriculation: **16/11/2017**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
20/09/2018	12.576	JACQUET AUTOMOBILES	CREMAILLE DE DIRECTION RPLT
			FERMETURE DOSSIER TECHNIQUE
			GEOMETRIE CTRL
			ADBLUE
			REVISION
			FILTRE CLIM RPLT