



**Volkswagen ID.3: R404FJ**

Vinnumber:	<b>VWZZZE1ZNP038943</b>	Versionname:	<b>ID.3 107kW / 62kWH Pro automaat</b>
First Registrationdate:	<b>29/08/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>98634</b>	Power Kw:	<b>107</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>603</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 95 / T / Aluminium	3,1 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	3,0 mm	Bridgestone	Summer
Rear	Left	215 / 55 / 18 / 95 / T / Aluminium	2,1 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	1,0 mm	Bridgestone	Summer


**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

**Service, Maintenance, Execute**



**Wing FL, Dent(s), Repair and paint (complete)**



**Wing RL, Scratch(es), Repair and paint (complete)**



Door RL, Scratch(es), Repair and paint (complete)



Tyre RL, Worn, Replace



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Tyre RR, Worn, Replace



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	R404FJ
<b>Merk Model</b>	Volkswagen ID.3 107kW / 62kWH Pro automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	29-08-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-07-24	45.769	Ruitenwischerblad(en) achterzijde