




Volkswagen Golf:

Vinnumber:	WVWZZZCDZMW356676	Versionname:	
First Registrationdate:	10/05/2021	Fiscalpower:	
Expertise Mileage:	82109	Power Kw:	110
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1405
Fueltype:	Hybrid Petrol		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/55/16/92 H				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	205/55 R 16 92 H			
Tyre size FR	205/55 R 16 92 H			
Tyre size RL	205/55 R 16 92 H			
Tyre size RR	205/55 R 16 92 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	1461,25
Service, Maintenance, Check	0,00



Seat cover FR, Stain, Cleaning	29,16
--------------------------------	-------



Door panel RL, Scratch(es), Smart repair	116,69
--	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Bonnet, Chemical polution, Repair and paint (complete)	406,19
--	--------



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------




Wing FL, Dent(s), Acceptable	0,00
------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------



Tailgate / Boot, Dent(s), Acceptable	0,00
--------------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

204,21

