



PEUGEOT PARTNER: GD-020-CW

Vinnumber:	VR3EFYHYCMJ909901	Versionname:	PEUGEOT PARTNER BLUEHDI 100 S&S 650KG
First Registrationdate:	24/11/2021		STAND ASPHALT VU [4P] bvm 5-102CH-5cv
Expertise Mileage:	151328		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	
Gearbox:	MAN 5 VIT	Power Kw:	75
Transmission:	Front	Body colour:	White
Fueltype:	Diesel	Paint type:	Opaque
Engine functioning:	Yes	Interior colour:	Grey
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Other: 30%	Fr.R.	Other: 30%
	Re.L.	Other: 30%	Re.R.	Other: 30%
Tyre profile depth FL				6.3
Tyre profile depth FR				6.2
Tyre profile depth RL				6.1
Tyre profile depth RR				6.1
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Interior, Stain, Chemical cleaning



Door panel FR, Scratch(es), Replace



Dashboard, Scratch(es), Replace



Glove compartment lid, Scratch(es), Replace



Floor mat F, Tear, Replace



Inner door sill FL, Scratch(es), Paint



Wheel cover FL, Missing, Replace



Side wall RL, Dent(s), Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Paint



Side wall RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Door trim FR, Scratch(es), Replace



Load compartment roof, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GD-020-CW** Date de 1ère immatriculation: **24/11/2021**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
26/09/2025	119.209	JL BURGANA	INJECTEUR ADBLUE RPLT
	0		RECYCLAGE
	0		DISQUES PLAQUETTES AV RPLT
12/09/2025	119.207	JL BURGANA	LIQUIDE DE FREIN
	0		REVISION
	0		FILTRE CLIM RPLT
	0		FILTRE A AIR RPLT
	0		REVISION
	0		DIVERS CLIM
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
05/04/2024	74.070	JL BURGANA	REVISION ET CLIM ET AIR ET CARBURANT
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		ADBLUE
18/04/2023	40.602	JL BURGANA	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		ADBLUE