

INSPECTION REPORT

End of contract

GENERAL INFO

File	314146
License plate	2CCT870
Vehicle identification number	VSSZZZKJZNR104338
Dossier	2022045026
Make	Seat Arona 1.0 81kW Move DSG
Mileage	126943
First registration	08/06/2022
client availability date	06/06/2026
inspectionDate	10/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
272	Bumper Front / Trim Right / Replace	N
540	Interior // Repair 1	N


Damage Pictures



Bumper Front // Smart Repair Large-scratch



Bumper Front / Trim Right / Replace-scratch



Interior // Repair 1-Incinerated