MACADAM









OPEL CORSA: GJ-646-AG

Vinnumber:	**VXKUBYHTKN4329083**	Versionname:	**OPEL CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**
First Registrationdate:	**18/08/2022**	Fiscalpower:	
Expertise Mileage:	**170572**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Luggage cover	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/55/16/91 V**			
	Fr.L.	**Other: 50%**	Fr.R.	**Other: 55%**
	Re.L.	**Goodyear: 50%**	Re.R.	**Goodyear: 55%**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**4.7**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.5**
Tyre size FL	**195/55 R 16 91 V**
Tyre size FR	**195/55 R 16 91 V**
Tyre size RL	**195/55 R 16 91 V**
Tyre size RR	**195/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Seat cover FR, Stain, Cleaning




Roof liner, Stain, Cleaning




Alloy rim FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Bumper F, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GJ-646-AG** Date de 1ère immatriculation: **18/08/2022**

Modèle: **Opel CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
20/03/2026	149.530	MONTELIMAR AUTO MONTELIMAR	PLAQUETTES AV RPLT
			REVISION
09/06/2026	148.924	CONTICLUB	GEOMETRIE CTRL
17/03/2026	148.914	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
05/08/2025	121.080	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
29/07/2025	120.477	MONTELIMAR AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
25/10/2024	89.363	MONTELIMAR AUTOMOBILES	BALAIS ESSUIE GLACE AV
			REVISION
			LIQUIDE DE FREIN
			DISQUES PLAQUETTES AV RPLT
22/01/2024	58.952	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
19/01/2024	54.230	MONTELIMAR AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
02/06/2023	36.809	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
25/04/2023	30.889	AUTO SERVICE DISTREENNE	REVISION ET CLIM