DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VXKFCYHZ6 R1048769	Registration date	23/07/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	WES-KW 613	Odometer	8 533 km
Model	ASTRA ST 1.5 Diesel 96kW GS Auto				

Inspection Details

Arrival Date	14/08/2026	Inspection ID	7127938	Inspection date	25/08/2026
Assign Date	14/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen

















Generic equipment

Removable element

Spare wheel kit	✓
Toolkit	✓
Load cover	✓

Technical Document


User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Barum 225/45/17 V All seasons 7.0 mm

Barum 225/45/17 V All seasons 7.0 mm






Barum 225/45/17 V All seasons 8.0 mm

Barum 225/45/17 V All seasons 8.0 mm

Exception / Damage

1



Part	Service 2	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Wing	Repair Time	0.50	Part Cost	-
Position	Front left	Repair Cost	70.00€	Gross Cost	70.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	70.00€	**Net Cost**	**70.00€**

3



Part	Interior tailgate lining	Repair Time	0.20	Part Cost	194.09€
Position	Up	Repair Cost	28.00€	Gross Cost	222.09€
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 33.31
Repair mode	Replace	Flat Rate	-	**Net Cost**	**188.78€**

4

Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

Summary Inspection

Gross Price	592.09€	Depreciation	-33.31€	Net Price	558.78€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.70	98.00€	4.29 %	-4.20€	93.80€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	494.09€	5.89 %	-29.11€	464.98€
Flat Rate	-300.00€	-	-	-300.00€