



Volkswagen Polo (UKL): 2CPQ824

Vinnumber:	WVWZZZAWZNU096116	Versionname:	Polo Life 1.0TSi 95pk/cv 5p
First Registrationdate:	10/10/2022	Fiscalpower:	
Expertise Mileage:	80802	Power Kw:	70
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	12000.0		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	185/65/15/88 H			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Missing, Replace



Bumper F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable



Wheel cover RR, Scratch(es), Replace



Wheel cover FR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Kenteken	2CPQ824
Merk Model	Volkswagen Polo Life 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/10/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/14/25	60,025	bougie	Vervangen
10/14/25	60,025	klein materiaal	
10/14/25	60,025	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
10/14/25	60,025	remblokken vooraan	Vervangen
10/14/25	60,025	ruitenwisserrubber vooraan	Vervangen
6/4/25	50,579	klein materiaal	
6/4/25	50,579	lambda sonde	Vervangen
4/17/25	47,436	diagnose	Uitvoeren
4/17/25	47,436	klein materiaal	N.v.t.
4/17/25	47,436	lambda sonde	Vervangen
12/30/24	38,444	diagnose	Uitvoeren
9/3/24	30,024	klein materiaal	
9/3/24	30,024	luchtfiler interieur	Vervangen
9/3/24	30,024	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
9/3/24	30,024	remvloeistof	Vervangen
9/3/24	30,024	ruitenwisserrubber achter	Vervangen
4/16/24	20,834	klein materiaal	Uitvoeren
4/16/24	20,834	ruitenwisserrubber vooraan	Vervangen