



RENAULT CLIO SOCIETE

Immatriculation	-
VIN	VF1RJA00068147714
Kilométrage	83 954 km
Première immatriculation	26/11/2021
Couleur carrosserie	Blanc

DÉTAILS DE L'INSPECTION

Adresse d'inspection	Date de l'inspection	02/06/2026 10:38:50
Adresse d'inspection		

INFORMATIONS SUR LE VÉHICULE

Marque	RENAULT	Type de carrosserie	Berline
Modèle	CLIO SOCIETE	Nbre portes	5
VIN	VF1RJA00068147714	Nbre sièges	2
Première immatriculation	26/11/2021	Transmission	Avant
Kilométrage	83 954 km	Couleur intérieur	Noir
Catégorie	Vehicule société	Couleur carrosserie	Blanc

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	1	Certificat immatriculation (original)	Non
Nbre clés télécommandes	1	Certificat immatriculation (original)	N/A

OPTIONS

Batterie fonctionnante	Oui	Stockage GPS	HD
Moteur fonctionnant	Oui	Stockage GPS	Oui
Véhicule roulant	Oui	Cache bagages	Oui
Niveau carburant	0	Cric	Oui
GPS	Oui	Nature de peinture	Opaque

PNEUS

Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	5,2 mm	Michelin	185/65 R 15 88 T	Eté	Tôle	Non
Avant	Droite	5,0 mm	Michelin	185/65 R 15 88 T	Eté	Tôle	Non
Arrière	Gauche	4,9 mm	Bridgestone	185/65 R 15 88 H	Eté	Tôle	Non
Arrière	Droite	3,4 mm	Bridgestone	185/65 R 15 88 H	Eté	Tôle	Non

DAMAGES




Outer sill R

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)




Bumper R

Damage type	Deformed / Strained
Repair mode	Repair and paint (complete)




Wing FR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)




Bumper F

Damage type	Scratch(es)
Repair mode	Repair and paint (complete)



Brand badge F

Damage type	Broken
Repair mode	Replace



Remote ignition key

Damage type	Missing
Repair mode	Repair/replace (lump sum)



Tyre RR

Damage type	Out of tolerance
Repair mode	Replace



Door panel RR

Damage type	Scratch(es)
Repair mode	Smart repair



Boot lid covering R

Damage type	Scratch(es)
Repair mode	Smart repair



Wheel cover FR

Damage type	Missing
Repair mode	Replace



Wheel cover RR

Damage type	Missing
Repair mode	Replace



Wheel cover RL

Damage type	Missing
Repair mode	Replace



Wheel cover FL

Damage type	Missing
Repair mode	Replace



Seat cover FR

Damage type	Stain
Repair mode	Cleaning



Seat cover FL

Damage type	Stain
Repair mode	Cleaning



Luggage cover stopper

Damage type	Missing
Repair mode	Replace



Instrument panel, complete


Damage type	Scratch(es)
Repair mode	Acceptable

Comments: griffes superficielles



Door trim FR

Damage type	Scratch(es)
Repair mode	Acceptable



Door RR

Damage type	Dent(s)
Repair mode	Acceptable

COMMERCIAL PHOTOS

