

INSPECTION REPORT

End of contract

GENERAL INFO

File	304814
License plate	2DPH906
Vehicle identification number	W1K5M8HBXPN402495
Dossier	2022269031
Make	Mercedes CLA SB 200 Business L
Mileage	74680
First registration	15/05/2023
client availability date	29/05/2026
inspectionDate	06/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	N
320	Wheel Two Tone Rear Left // Repair	N
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Roof // Smart Repair Medium-dent



Wing Rear Right // Repair & Painting-dent




Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked



Front Bonnet // Polish-Chemical reaction




Interior Cleaning // Small-dirty



Trunk Compartment / Side Cover Right / Replace-tear



Rear Bonnet // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch