



## PEUGEOT 20

Vinnnumber:	VR3UPHNEKMT003341	Versionname:	1.2 PureTech 100 MAN6 S&S GT
First Registrationdate:	21/01/2021	Fiscalpower:	
Expertise Mileage:	89481	Power Kw:	74
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3307
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

## Options

Number of keys total	2	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

## Limited Technical Inspection

## Tyres

205/45/17/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/45 R 17 92 H
Tyre size FR				205/45 R 17 92 H
Tyre size RL				205/45 R 17 92 H
Tyre size RR				205/45 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

## Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1546,59
Bonnet, Chemical pollution, Polish	0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Wheel cover RL, Scratch(es), Acceptable 0,00



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Boot cover, Missing, Replace 205,69



Bumper moulding R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



77,26



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Wheel cover FR, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Repair and paint (complete) 356,62



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Roof, Dent(s), Acceptable 0,00



Aerial, Missing, Replace 90,18

