


2-FTF-052

2-FTF-052 · ST LINE 1.0 155PS AT / Metallic · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FTF-052	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRD36743
Model	Focus	Cylinder Capacity	999 ^{cm3}
Model Versions	ST LINE 1.0 155PS AT / Metallic	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	13-08-2024
Body Type	5 door hatchback	Odometer	66.273 ^{Km}
Color	Silver	Numer Of Keys	2
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	114		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel – Heated

Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	2 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Alloy - Right Rear

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Skirt - Right

Damage Type



Dent(s) & Scratch(es)

Notes

Ontzet

Repair Type Acceptable

Panelbeating No
& Spray



Damage Part

Alloy - Right Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Dislocated / Loose

Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type


Acceptable

Fender - Rear Left

Small dent(s)

Restyle

No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No