



Volvo XC40: L117PB

Vinnumber:	VV1XZEDVEM2596462	Versionname:	XC40 P8 Recharge 300kW AWD automaat
First Registrationdate:	6/07/2021	Fiscalpower:	
Expertise Mileage:	111624	Power Kw:	300
Bodytype:		Body colour	Fusion Red metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	415
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	3	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Sun Roof electric
Radio multimedia		Panoramic roof
		Rear parking sensors
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 19 / 104 / V / Aluminium	5,2 mm	Continental	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	5,3 mm	Continental	Summer
Rear	Left	255 / 45 / 19 / 104 / V / Aluminium	3,6 mm	Continental	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	3,6 mm	Continental	Summer


Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Replace and paint



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Bumper corner RR, Scratch(es), Repair and paint (complete)



Kenteken	L117PB
Merk Model	Volvo XC40 P8 Recharge 300kW AWD automaat
Brandstofsoort	Elektrisch
Datum deel1	06-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
28-10-25	90.961	Ruitenwischerblad(en) achterzijde
28-10-25	90.961	Ruitenwischerblad(en) voorzijde
02-07-25	84.803	APK
02-07-25	84.803	Onderhoudsbeurt
02-04-25	81.065	Boordcomputer
17-12-24	77.000	Vervanging band
15-04-24	28.513	Onderhoudsbeurt
15-04-24	28.513	Remvloeistof
28-07-23	42.775	Reparatie band(en)
23-01-23	28.512	Onderhoudsbeurt
08-10-21	4.641	Vervanging band