MACADAM







BMW X5 xDrive45e: 2CGG949

Vinnumber:	**WBATA610709L36782**	Versionname:	
First Registrationdate:	**13/07/2022**	Fiscalpower:	
Expertise Mileage:	**97503**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:			
Maintenance	**OK**		
Maintenance	**6000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**1**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**265/50/19/110 H**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Bridgestone: 6 mm**	Re.R.	**Bridgestone: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**265/50 R 19 110 H**
Tyre size FR	**265/50 R 19 110 H**
Tyre size RL	**265/50 R 19 110 H**
Tyre size RR	**265/50 R 19 110 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**1**	Runflat	**Yes**
Number of charging cables (rapid charge)	**1**		

Interior, Damaged, Acceptable







Bumper moulding F, Scratch(es), Acceptable




Alloy rim RL, Scratch(es), Repair and paint (complete)






Internal boot lining L, Tear, Replace




Tailgate / Boot, Scratch(es), Polish




Tailgate / Boot, Dent(s), Paintless dent repair




Alloy rim RR, Scratch(es), Repair and paint (complete)








Alloy rim FR, Scratch(es), Repair and paint (complete)








Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Paintless dent repair

