

INSPECTION REPORT




End of contract


GENERAL INFO

File	315388
License plate	2CXZ070
Vehicle identification number	VF1RJA00769796131
Dossier	2022206082
Make	Renault Clio TCe 90 Techno
Mileage	51901
First registration	10/01/2023
client availability date	15/06/2026
inspectionDate	18/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
75	Side View Mirror Left // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
211	Door Front Right // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	Y


Damage Pictures



Side View Mirror Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch





Bumper Rear // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Front Right // Smart Repair Medium-dent



Door Front Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Painting-stone chipping