MACADAM









PEUGEOT 5008: FX-557-YP

Vinnumber:	**VF3MCYHZUMS071614**	Versionname:	**PEUGEOT 5008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**18/03/2021**	Fiscalpower:	
Expertise Mileage:	**204255**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**Green**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**7**		
Number head rests	**7**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/103 V**			
	Fr.L.	**Michelin: 55%**	Fr.R.	**Michelin: 60%**
	Re.L.	**Michelin: 90%**	Re.R.	**Michelin: 80%**

Tyre profile depth FL	**4.6**
Tyre profile depth FR	**4.2**
Tyre profile depth RL	**2.0**
Tyre profile depth RR	**2.9**
Tyre size FL	**225/55 R 18 103 V**
Tyre size FR	**225/55 R 18 103 V**
Tyre size RL	**225/55 R 18 103 V**
Tyre size RR	**225/55 R 18 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Interior, Stain, Cleaning








Seat cover FL, Tear, Replace




Malfunction indicator, Blinking, Check



Dashboard, Glue residues, Acceptable




Alloy rim FL bitone/polychrome, Scratch(es), Acceptable





Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Tyre RL, Out of tolerance, Replace




Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Tyre RR, Out of tolerance, Replace




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Wing FL, Scratch(es), Paint




Door FL, Scratch(es), Paint




Door RL, Scratch(es), Polish




Windscreen, Stone chip(s), Windscreen repair




Bumper moulding F, Broken, Replace




Wing RR, Scratch(es), Paint




Wing trim RR, Scratch(es), Replace




Door RR, Scratch(es), Paint




Door FR, Scratch(es), Paint




Bumper R, Scratch(es), Acceptable






ALPHABET

Historique Maintenance

Immatriculation: **FX-557-YP** Date de 1ère immatriculation: **18/03/2021**

Modèle: **Peugeot 5008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
23/02/2026	198.358	SARL GARAGE DELAPORTE	REVISION ET CLIM ET AIR ET CARBURANT
15/10/2025	180.482	SARL GARAGE DELAPORTE	KIT DISTRIBUTION RPLT
	0		KIT ACCESSOIRES RPLT
29/09/2025	178.967	SARL GARAGE DELAPORTE	REVISION
24/03/2025	157.070	SARL GARAGE DELAPORTE	REVISION
	0		PLAQUETTES AV RPLT
15/07/2024	135.303	SARL GARAGE DELAPORTE	BALAI ESSUIE GLACE AR
	0		REVISION ET CLIM ET AIR ET CARBURANT
15/12/2023	112.983	SARL GARAGE DELAPORTE	BALAIS ESSUIE GLACE AV
	0		REVISION
	0		PLAQUETTES AR RPLT
03/04/2023	92.039	SARL GARAGE DELAPORTE	DISQUES PLAQUETTES AV RPLT
	0		REVISION
12/10/2022	69.986	SARL GARAGE DELAPORTE	BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM
11/04/2022	44.887	SARL GARAGE DELAPORTE	REVISION