MACADAM










VOLKSWAGEN ID.4: GJ-434-TG

Vinnumber:	**WVGZZZE2ZNE005811**	Versionname:	**VOLKSWAGEN ID.4 77 kWh 174ch Pro Business VP [5P] bva 1-174CH-5cv (SUV)**
First Registrationdate:	**29/09/2022**	Fiscalpower:	
Expertise Mileage:	**90576**	Power Kw:	**128**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Back**	Interior colour	**Black**
Fueltype:	**Electric**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Leather** **Lining Alcantara**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/55/19/101 T**			
	Fr.L.	**Hankook: 25%**	Fr.R.	**Hankook: 35%**
	Re.L.	**Hankook: 30%**	Re.R.	**Hankook: 35%**

Tyre profile depth FL	**6.5**
Tyre profile depth FR	**5.8**
Tyre profile depth RL	**6.1**
Tyre profile depth RR	**6.0**
Tyre size FL	**235/55 R 19 101 T**
Tyre size FR	**235/55 R 19 101 T**
Tyre size RL	**255/50 R 19 103 T**
Tyre size RR	**255/50 R 19 103 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Interior covering B pillar L, Scratch(es), Replace





Door panel FL, Scratch(es), Replace






Interior covering B pillar R, Scratch(es), Replace





Tailgate / Boot, Dent(s), Repair and paint (complete)





Charging cable (normal), Missing, Replace




ALPHABET

Historique Maintenance

Immatriculation: **GJ-434-TG** Date de 1ère immatriculation: **29/09/2022**

Modèle: **Volkswagen ID.4 77 kWh 174ch Pro Business VP [5P] bva 1-174CH-5cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
22/07/2026	85.664	SARL D'EXPLOITATION AMTC-BDA	Autre
			Filtre d'habitacle (Remplacement)
			Filtre à Pollen
			Entretien - Standard
			Pieces
			Liquide de frein (Remplacement)
			Liquide de lave -glace
			REVISION
			LIQUIDE DE FREIN
			LIQUIDE LAVE GLACE
22/07/2026	85.664	SARL D'EXPLOITATION AMTC-BDA	Frais de participation à l'environnement
05/06/2026	81.909	SARL D'EXPLOITATION AMTC-BDA	BALAI ESSUIE GLACE AR
31/10/2025	67.101	SARL D'EXPLOITATION AMTC-BDA	BALAIS ESSUIE GLACE AV
02/07/2024	43.767	ETS DUGAST	BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			RECYCLAGE
			REVISION